

Incident Investigation Report: Valve GV-304 Failure

Document ID: INC-2023-014

Failure Date: June 10, 2023

Investigator: H. R. Sharma (Safety Officer)

Equipment Tag: GV-304 (Gate Valve Unit-4 Hydrocracker)

Event Description:

On June 10, 2023, a hydrocarbon leak was detected around gate valve GV-304.

The emergency shutdown (ESD) loop was activated to isolate the line.

Root Cause Analysis:

Investigation revealed packing corrosion.

The valve had missed its scheduled 12-month inspection which was due in May 2023.

Failure occurred due to lack of preventive maintenance inspection.

Corrective Actions:

1. Replaced GV-304 gland packing. Tested hydrostatic seal (OK).
2. Safety Officer H. R. Sharma revised the Factory Act compliance checklist to enforce calendar alerts for annual valve testing.
3. Conducted training for operations team on ESD loop testing.

Signed: H. R. Sharma