

Safety Standard: Hot Work Permit Procedure

Document ID: HSE-STD-005

Regulation Reference: OISD-118 Section 5.1

Author: Safety Audit Division

1.0 Purpose

This procedure defines the requirements for hot work permits before carrying out welding, cutting, or grinding operations in hazardous plant areas.

2.0 Compliance Requirements

- Ref: OISD-118 Section 5.1: Hot work permits must be issued for all welding, cutting, or grinding operations.
- Before issuing a permit, a portable fire extinguisher must be deployed at the job site.
- Gas testing must be performed to check H₂S and LEL (combustible gas) levels.
- Fire watch must be stationed at the site during and 30 minutes after completion of work.