

High vibration corrected by alignment (P-2210)

Incident Report | Tier 1

1. Asset

Field	Value
Asset tag	P-2210
Name	Resin transfer pump
Class	CP200
Plant / Unit / Area	MV / U200 / Blending
Service duty	Hot organics transfer - hot resin blend, 160 C
Criticality	B
Installed on	2020-08-03

2. Findings

P-2210 tripped on high drive-end vibration (WO-2024-0662). Laser alignment found the coupling out by 0.4 mm; corrected with shims. This is a misalignment event, NOT a seal failure - distinct from the mechanical-seal pattern on the other three sisters.

3. Recommendation

Verify the seal flush plan on this and the sister CP200 pumps against the OEM MSC-CP200 manual (API Plan 11) and correct any field deviation before further seal replacement.