

SOP-003 - Lockout / Tagout (LOTO) Procedure

Standard Operating Procedure | Tier 1

1. Purpose

To ensure equipment is isolated from all energy sources before maintenance.

2. Procedure

1. Identify all energy sources for the equipment (electrical, mechanical, hydraulic, thermal, stored).
2. Notify affected personnel of the shutdown.
3. Shut down the equipment using normal stopping procedure.
4. Isolate each energy source at the disconnecting means.
5. Apply an individual lock and tag to each isolation point.
6. Release or restrain stored energy (pressure, springs, thermal).
7. Verify isolation by attempting a normal start (try-out); confirm zero energy.
8. Carry out the maintenance work.
9. On completion, remove tools, replace guards, and remove locks/tags only by the person who applied them.
10. Notify affected personnel before re-energising.