

OWNER: WHORLE CA	ieuen	6 Congressional Ave., cor. Viseyes Ave. 6rgy, Bahay Toro 1, Quezon City Tels. 925-4557 + 4540227 QUOTATION FORM TEL. NO.:			No. 179246	
MAKER: TOYOTO	HACE	MODEL:		YEAR:	PLATE NO:	
ADDRESS:	ок	COMMENTS	PARTS	LABOR	REMARKS	
PARTS DESCRIPTION	- OK	COMMENTO	174110		The state of the s	
Suspension Bushing / Assy					CUSTOMER'S COMPLAINT	
Tie Rod End					,	
Rack End	1				115 FORKE RAST	
Steering Boot					TTO I JOHN LIE	
Ball Joint		V. (1) (40)	Vaccinia.	0 1	YokoHama	
Shock Absorber Shock Mounting		12650	days	order	Int-nilouture.	
Brake Pads		O.F.				
Rotor Disc		Downpaym	0.1	March	011175	
Brake Shoe / Brake Drum		- Jumithan Man	CH.	CUMONF3	8,883.75	
Caliper Kit / Piston		1			-UN	
Idler Arm		14		1500	* 2	
		-	The same			
Pitman Arm Center Post / Link					17.767.50	
Stabilizer Link / Bar Bushing	1				17,701	
The state of the s					+ 810 - tinggar 4 pito	
CV Joint / Cross Joint	-				1 00 - 10	
Axle Boot	1	-			TECHNICIAN RECOMMENDATION	
Wheel Bearing						
Mounting / Dismounting					( P. FUO. 81 )	
Rotation	1				(12,007)	
Balancing						
Clutch Disc					8,652 CAN	
Pressure Plate				4	B. US - CACH	
Release Bearing					X 3	
rankshaft Oil Seal	100					
ilot Bearing			1000		7.304	
iming Belt		F12 42 - 10			t am lines to ate	
amshaft / Crankshaft Oil Seal	1				+ 300 - tingsa 4 pt	
ensioner / Idler Bearing					-	
					(17, LOU)	
an Belts						
ngine Support			30.00			
ansmission Support	3	27			TOTAL PARTS	
lve Cover / Oil Pan Gasket				-	TOTAL LABOR	
gnment (Toe In/Out)	Y			350	TOTAL AMDUNT	
mber				1000		
	9		-		(1,650)	
ster	4		3	(300)	TECHNICIAN:	
preceding cost assessments ear which are not o	are bas	ed on visual Insp at the tim	ection on	ly. As the w	ork progresses "hidden defects" may spection. Please be guide.	
forme:				and the same	guide.	
			Prepa	red by:	Tucca	
Gustomer Signature					Sales Service Personnel	