AI SITE HISTORY REPORT

502 Church Road, Taigum QLD

Generated 07 Apr 2026 | Lat -27.333805, Lng 153.048571 | Confidence: Medium

Executive Summary

The site at 502 Church Road, Taigum QLD features a historically clear presence of two adjacent ponds on the eastern side of the site, both still visible in current imagery. A notable former pond to the north of the main ponds shows signs of infilling and vegetative encroachment over time.

On-site: Presence of two active ponds on the eastern side of the site, confirmed from 1995 to current. An additional former pond north of these ponds shows partial infilling and vegetated transition since 1995,

representing a more significant geotechnical risk.

Adjacent / context: Immediately adjacent northeast is a linear water body likely serving as a drainage or creek channel. Off-site to the southeast is a large pond, possibly used for farm or stormwater management purposes.

Site Details

Address	502 Church Road, Taigum QLD
Location source	polygon
Latitude / Longitude	-27.333805, 153.048571
Site bbox	267.6 m × 274.6 m
Context bbox	321.6 m × 328.6 m
Polygon supplied	Yes

Key Flags

Key Flag	Level	Comment
Former water features	High	Former water features interpreted from historical imagery, including at least one area now absent in recent imagery.
Vegetation / land change	Low	Vegetation and land cover change is visible between image dates.
Fill / disturbance	Moderate	Evidence of earthworks and disturbed ground surfaces near the southern central part of the site related to building activity and material stockpiles.

Flag Summary

Potential Fill / Disturbance	**Moderate**
Evidence of earthworks and disturbed ground surfaces near the southern central part of the site related to building activity and material stockpiles.	
Former Water Features	**High**
Former water features interpreted from historical imagery, including at least one area now absent in recent imagery.	
Vegetation / Land Change	**Low**

Vegetation and land cover change is visible between image dates.

Screening Outcome

Multiple former water-feature indicators were identified on-site. Detailed geotechnical investigation is strongly recommended.

Primary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Active Pond A	former_pond	on_site	high	Clearly visible open water in historical and current imagery with defined vegetated edges, on east side of site.
Active Pond B	former_pond	on_site	high	Neighbor pond south of Active Pond A, clearly present with open water and vegetated edge from historical to current imagery.

Secondary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Earthworks Disturbance Area	probable_pond	on_site	medium	Area of grading, stockpiles, and ground disturbance just south of ponds near buildings indicating possible fill or earthworks.

Adjacent Contextual Influences

Feature	Type	Relation	Confidence	Notes
Former Pond C	former_pond	adjacent	high	Northwest of the active ponds, an irregular circular feature with vegetative encroachment and no persistent open water. Seen as open water in 1995 imagery but has progressively become vegetated, indicating infilling.
Adjacent Linear Drainage Feature	drainage_feature	adjacent	high	Northeast boundary near Cabbage Tree Creek shows a narrow linear drainage or creek feature running roughly NW-SE parallel to Church Road.

Feature Timeline

Former Pond C — 1995: open water clearly visible

Former Pond C — 2011: open water faded with more vegetation encroachment

Former Pond C — 2021: mostly vegetated with no open water visible

Active Pond A — 1995-2021: persistently visible open water with stable vegetation boundaries

Active Pond B — 1995-2021: persistently visible open water with stable vegetation boundaries

Detailed Findings

Visible Observations

• Two active ponds on eastern area with open water and vegetated edges

• Former pond north of active ponds now vegetated with no open water

• Earthworks and disturbance near buildings in southern central area

• Adjacent northeast linear water body likely drainage or creek

• No visible retaining walls, batters, or slope instability features

Overall Change Timeline

1995-2021: Former pond north of active ponds transitioned from open water to vegetated, infilled condition.

1995-2021: Two eastern ponds remain consistent with open water and vegetation boundaries.

2015-2021: Increased earthworks and disturbance near central south area, likely related to site structures.

Possible Geotechnical Implications

• Former pond or infilled basin signatures may indicate fill, uncontrolled fill, deep fill, soft ground, or moisture-sensitive soils.

• possible soft or moisture-sensitive soils in former pond area (Former Pond C)

• moisture variability and local wetness near active ponds

• ground variability and compaction issues near disturbance zones

Recommended Follow-Up

• Detailed geotechnical investigation is strongly recommended based on identified site history risks.

Supporting Imagery

current_wide_context — current

Source: mapbox_bbox_wide_context

current_context — current

Source: mapbox_bbox_context

current_subzone_nw — current

Source: mapbox_bbox_subzone

current_subzone_west — current

Source: mapbox_bbox_subzone

current_site — current

Source: mapbox_bbox_site

historical_qld_followup_1 — 1995 (1995-06-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | Resolution: 60 2

historical_qld_followup_4 — 2015 (2015-05-30)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2015_10cm_SISP_LGA | Resolution: 10 2

historical_qld_followup_6 — 2021 (2021-07-17)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | Resolution: 10 2

Limitations & Disclaimer

- Imagery resolution limits detection of small slope instability or subtle fill edges.
- No ground truth or detailed topographic data available to confirm pond depths or soil conditions.
- Vegetation cover variability may obscure some former pond boundaries.
- Historical imagery intervals are irregular which may miss some intermediate site changes.

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.