AI SITE HISTORY REPORT

502 Church Road, Taigum QLD

Generated 07 Apr 2026 | Lat -27.333805, Lng 153.048571 | Confidence: Medium

Executive Summary

The site at 502 Church Road, Taigum QLD, features one circular water body on-site visible in all historical and current imagery, with clear evidence of two distinct ponds in historical images around 1995-2009. These water bodies have reduced in size and appear to have been partly infilled over time. Surrounding land shows signs of earthworks and fill activities. Adjacent to the site, there is a narrow water feature along the creek corridor to the north and a probable pond or waterbody just east of the site boundary by the Gateway Bikeway/M1 corridor. No significant vegetation clearing was observed within the site boundary, but moderate disturbance including fill

and earthworks is apparent. Additional targeted remainder-lot rescan identified further possible buried / former pond risk areas requiring field confirmation.

On-site: One prominent circular pond is consistently visible on-site throughout historical and current imagery, though its water extent has diminished over time, indicating possible infilling and disturbance. Evidence of fill or disturbance exists around the pond, especially on the eastern side near Church Road, associated with construction-like debris. The southern half of the site appears as managed or pasture land with no water or disturbance features. No additional ponds or fill areas are clearly visible. Targeted rescan placed greater emphasis on secondary former pond / buried basin risk areas.

Adjacent / context: Adjacent to the site, a narrow water feature (likely a creek) runs along the northwest boundary outside the site polygon. To the east, near the Gateway Bikeway/M1 corridor, a separate waterbody or pond is visible, likely off-site and not directly linked to site drainage. No other significant adjacent fill or pond features are evident.

Site Details

Address	502 Church Road, Taigum QLD
Location source	polygon
Latitude / Longitude	-27.333805, 153.048571
Site bbox	267.6 m × 274.6 m
Context bbox	321.6 m × 328.6 m
Polygon supplied	Yes

Key Flags

Key Flag	Level	Comment
Former water features	Elevated	Two circular pond features were visible from 1995 aerial imagery; one has diminished substantially in water coverage, indicating partial infilling.
Vegetation / land change	Low	No major clearing detected on-site, natural vegetation mainly around pond edges and adjacent creek corridor.
Fill / disturbance	Elevated	Evidence of fill or construction debris disturbance on east side of on-site pond near road access.

Flag Summary

Potential Fill / Disturbance	**Elevated**
Evidence of fill or construction debris disturbance on east side of on-site pond near road access.	

Former Water Features	**Elevated**
Two circular pond features were visible from 1995 aerial imagery; one has diminished substantially in water coverage, indicating partial infilling.	

Vegetation / Land Change	**Low**
No major clearing detected on-site, natural vegetation mainly around pond edges and adjacent creek corridor.	

Screening Outcome

Site displays likely former ponds with significant reduction in water extent and evidence of infilling and fill disturbance on-site, indicating potential geotechnical risk areas requiring further investigation for soft soils and fill stability.

Primary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Pond C	former_pond	on_site	medium	Secondary smaller pond evident in historical imagery but not clearly visible in current imagery, likely infilled.

Secondary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Disturbance Area	disturbance	on_site	medium	Area with construction debris and disturbed land east of the pond near Church Road suggests possible fill or earthworks.

Adjacent Contextual Influences

Feature	Type	Relation	Confidence	Notes
Pond B	former_pond	adjacent	high	Clearly visible water body in historical 1995 imagery near center-east part of site, no distinct water footprint in current imagery, likely infilled.
Pond D	pond	adjacent	medium	Water body adjacent to the east, outside site boundary near Gateway Bikeway, visible in current and historical imagery.
Pond A	pond	adjacent	high	Narrow drainage feature (likely Cabbage Tree Creek) along the northwest adjacent to site polygon.

Detailed Findings

Visible Observations

• Circular pond with surrounding vegetation on east side of site.

• Fill/disturbance area with construction debris along Church Road access.

• Narrow drainage creek corridor to northwest adjacent site.

• Former pond (water_feature_2) present in 1995 aerial imagery shows a clear water body with a circular shape but no standing water in current imagery.

• Current small pond (water_feature_1) near eastern site boundary visible in recent images.

• Areas of disturbed soil or fill near existing buildings on site.

Overall Change Timeline

1995–2009: Two distinct ponds visible historically with full water coverage.

2009–current: Reduction in pond water coverage; secondary smaller pond likely infilled.

General: Fill/disturbance near pond evident only in more recent imagery.

General: Overall site converted to managed grass/pasture with limited new clearing.

Possible Geotechnical Implications

• Former pond signatures may indicate fill, uncontrolled fill, deep fill, soft ground, or moisture-sensitive soils.

Recommended Follow-Up

• Detailed geotechnical investigation is strongly recommended based on identified site history risks.

Supporting Imagery

current_wide_context — current

Source: mapbox_bbox_wide_context

current_context — current

Source: mapbox_bbox_context

current_subzone_nw — current

Source: mapbox_bbox_subzone

current_subzone_west — current

Source: mapbox_bbox_subzone

current_site — current

Source: mapbox_bbox_site

historical_qld_followup_1 — 1995 (1995-06-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | Resolution: 60 2

historical_qld_followup_5 — 2009 (2009-09-13)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2009_15cm_SISP_LGA | Resolution: 15 2

historical_qld_followup_8 — 2015 (2015-05-30)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2015_10cm_SISP_LGA | Resolution: 10 2

Limitations & Disclaimer

- Imagery resolution limits fine detail interpretation of small fill areas.
- No in-situ or subsurface data available; risk assessment is preliminary.
- Temporal gaps in imagery years limit exact timing of infilling and fill events.
- Imagery resolution limits detection of very small or shallow depressions.
- No subsurface data available; interpretations are surface morphology based.
- Exact fill material characteristics cannot be determined from imagery.

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.