AI SITE HISTORY REPORT

502 Church Road, Taigum QLD

Generated 07 Apr 2026 | Lat -27.333805, Lng 153.048571 | Confidence: High

Executive Summary

Site contains a prominent circular water feature on the northeastern side within property boundaries that appears consistent in shape and size from 1995 to current imagery. Adjacent to the east is a narrow elongated water feature aligned with a creek and bikeway. Several piles of material and cleared earth disturbance exist within the site interior and along the road frontage. Historical imagery confirms the presence of water bodies historically with some changes in water coverage details. Additional targeted remainder-lot rescan identified further possible buried / former pond risk areas requiring field confirmation.

On-site: One clearly visible circular water feature with vegetative margins on the northeastern side. Earthworks and disturbance with material piles near the center-right area. Cleared land with ongoing vegetative cover variations. Targeted rescan placed greater emphasis on secondary former pond / buried basin risk areas.

Adjacent / context: To the east outside site boundary, there is a narrow elongated water body aligned with Cabbage Tree Creek and Gateway Bikeway infrastructure, indicating drainage or creek features. Residential areas and parkland to the south and southwest.

Site Details

Address	502 Church Road, Taigum QLD
Location source	polygon
Latitude / Longitude	-27.333805, 153.048571
Site bbox	267.6 m × 274.6 m
Context bbox	321.6 m × 328.6 m
Polygon supplied	Yes

Key Flags

Key Flag	Level	Comment
Former water features	High	Circular water bodies consistently visible in historical images from 1995 to present within site.
Vegetation / land change	Moderate	Some clearing activities mainly near center and along road frontage detected in recent imagery.
Fill / disturbance	Elevated	Material piles and disturbed ground visible in recent images near the existing sheds.

Flag Summary

Potential Fill / Disturbance	**Elevated**
Material piles and disturbed ground visible in recent images near the existing sheds.	

Former Water Features	**High**
Circular water bodies consistently visible in historical images from 1995 to present within site.	

Vegetation / Land Change	**Moderate**

Some clearing activities mainly near center and along road frontage detected in recent imagery.

Screening Outcome

The site has a stable historic water feature (circular pond) and some recent disturbance related to material storage or clearing. Adjacent drainage features exist but no expanded historical pond loss or major fill observed within site.

Primary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Pond A	former_pond	on_site	high	Prominent circular water body with vegetated margins, visible consistently from 1995 through all recent imagery.
Pond B	former_pond	on_site	high	Smaller irregular water body-like feature visible near main pond, darker vegetation indicating potential water or wet area.

Secondary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Disturbance Area	disturbance	on_site	high	Pile of material and cleared ground near the center-right side of the site displayed in all current images.

Adjacent Contextual Influences

Feature	Type	Relation	Confidence	Notes
Adjacent Creek	drainage_feature	adjacent	high	Narrow elongated water body along the eastern boundary near Gateway Bikeway and creek line, resembling a drainage channel.
Disturbance Area	disturbance	adjacent	medium	Patch of cleared soil or fill located near south-eastern boundary close to Church Road, no standing water but irregular soil tones and lack of vegetation.

Detailed Findings

Visible Observations

- One stable circular pond with vegetation margin
- Smaller secondary water feature close to pond
- Cleared/disturbed soils at southeast side
- Adjacent natural creek to east

Overall Change Timeline

General: Primary pond persistent from at least 1995 to 2021

General: Minor changes in surrounding vegetation and cleared areas over time

Possible Geotechnical Implications

- Former pond signatures may indicate fill, uncontrolled fill, deep fill, soft ground, or moisture-sensitive soils.

Recommended Follow-Up

- Detailed geotechnical investigation is strongly recommended based on identified site history risks.

Supporting Imagery

current_wide_context — current

Source: mapbox_bbox_wide_context

current_context — current

Source: mapbox_bbox_context

current_subzone_nw — current

Source: mapbox_bbox_subzone

current_subzone_west — current

Source: mapbox_bbox_subzone

current_site — current

Source: mapbox_bbox_site

historical_qld_followup_1 — 1995 (1995-06-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | Resolution: 60 2

historical_qld_followup_4 — 2015 (2015-05-30)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2015_10cm_SISP_LGA | Resolution: 10 2

historical_qld_followup_6 — 2021 (2021-07-17)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | Resolution: 10 2

Limitations & Disclaimer

- No older historical imagery beyond 1995 available to screen prior pond existence before 1995.
- Image resolution limits precise boundary of small water/disturbance features
- No fall/rise topography data available to assess basin depth
- Absence of recent capture dates for some subzones

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.