AI SITE HISTORY REPORT

502 Church Road, Taigum QLD

Generated 07 Apr 2026 | Lat -27.333805, Lng 153.048571 | Confidence: Medium

Executive Summary

Site has a notable circular water feature NE quadrant, visible consistently from historical 1995 through recent 2021 imagery. Other smaller water bodies appear off-site nearby. Some clearing and disturbance evident on site but no major fill areas detected. Additional targeted remainder-lot rescan identified further possible buried / former pond risk areas requiring field confirmation.

On-site: One prominent circular water candidate in NE quadrant of the site appears vegetated and partially filled but consistently present since 1995. Additional scattered cleared soil/disturbance patches identified around the site. No large dams or ponds besides the circular water feature. Targeted rescan placed greater emphasis on secondary former pond / buried basin risk areas.

Adjacent / context: Adjacent includes creek to N and NE, additional open water bodies east off-site and some cleared/disturbed areas west and south with residential surrounds.

Site Details

Address	502 Church Road, Taigum QLD
Location source	polygon
Latitude / Longitude	-27.333805, 153.048571
Site bbox	267.6 m × 274.6 m
Context bbox	321.6 m × 328.6 m
Polygon supplied	Yes

Key Flags

Key Flag	Level	Comment
Former water features	Elevated	The circular water feature present since 1995 is a likely former pond/dam with stable morphology, other smaller dams visible nearby historically.
Vegetation / land change	Moderate	Signs of clearing and vegetation disturbance over time mainly in central and south site parts.
Fill / disturbance	Moderate	Some disturbed soil patches and cleared areas suggest local fill or minor earthworks on-site.

Flag Summary

Potential Fill / Disturbance	**Moderate**
Some disturbed soil patches and cleared areas suggest local fill or minor earthworks on-site.	

Former Water Features	**Elevated**
The circular water feature present since 1995 is a likely former pond/dam with stable morphology, other smaller dams visible nearby historically.	

Vegetation / Land Change	**Moderate**
Signs of clearing and vegetation disturbance over time mainly in central and south site parts.	

Screening Outcome

Site has a prominent longstanding water feature likely a former pond/dam and moderate soil disturbance. Recommended further onsite evaluation for geotechnical risk.

Primary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Pond A	former_pond	on_site	high	Prominent circular water body in NE quadrant with vegetated edges, persistent since 1995, partially filled but retaining water signature
Pond B	former_pond	on_site	high	Prominent circular water body in NE quadrant; vegetated edges, persistent water signature since 1995, partially filled but retains water.
Pond C	former_pond	on_site	medium	Smaller water pond south of main pond visible in 1995 historical image with some water signature, less visible or dry in recent images.

Secondary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Disturbance Area	disturbance	on_site	medium	Cleared soil/disturbed ground several patches spanning central and southern parts of site, possible earthworks or fill activity
Disturbance Area	disturbance	on_site	medium	Several patches of cleared/disturbed soil footprints in center and south of site; no water visible.

Adjacent Contextual Influences

Feature	Type	Relation	Confidence	Notes
Adjacent Pond 1	former_pond	adjacent	medium	Small elongated pond east of site beyond Church Rd, somewhat murky water, visible in recent imagery

Detailed Findings

Visible Observations

- One large circular water body on-site NE quadrant.
- Multiple cleared/disturbed soil patches across site.
- Creek runs adjacent to north boundary.
- Additional elongated small pond visible off-site east.

Overall Change Timeline

General: Circular water feature consistent presence from 1995 to 2021 though partial filling/vegetation changes noted.

General: Increased soil clearing/disturbance observed from after 2011 imagery onwards.

Possible Geotechnical Implications

• Former pond signatures may indicate fill, uncontrolled fill, deep fill, soft ground, or moisture-sensitive soils.

Recommended Follow-Up

• Detailed geotechnical investigation is strongly recommended based on identified site history risks.

Supporting Imagery

current_wide_context — current

Source: mapbox_bbox_wide_context

current_context — current

Source: mapbox_bbox_context

current_subzone_nw — current

Source: mapbox_bbox_subzone

current_subzone_west — current

Source: mapbox_bbox_subzone

current_site — current

Source: mapbox_bbox_site

historical_qld_followup_1 — 1995 (1995-06-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | Resolution: 60 2

historical_qld_followup_4 — 2015 (2015-05-30)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2015_10cm_SISP_LGA | Resolution: 10 2

historical_qld_followup_6 — 2021 (2021-07-17)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | Resolution: 10 2

Limitations & Disclaimer

- Limited availability of some historical images with lower resolution.
- Water presence confidence medium, partial vegetation may obscure extent.
- Disturbance signals could represent different activities not confirmed above-ground.
- Limited image resolution in historical images impacts precise boundary delineation for smaller features.
- Some disturbed surface soils may obscure subtle water signatures.

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.