AI SITE HISTORY REPORT

502 Church Road, Taigum QLD

Generated 08 Apr 2026 | Lat -27.333805, Lng 153.048571 | Confidence: High

Executive Summary

The site at 502 Church Road, Taigum QLD contains a circular water feature with historical evidence of water presence from at least 1995 through to recent years. There are signs of earth disturbance, particularly around the southern-central part of the site near a small building and materials pile. Adjacent to the site to the east is vegetation and additional water features visible as ponds or drainage near Cabbage Tree Creek. The historical imagery shows consistent presence of ponds with some change in water extent and coloration over time. Additional targeted remainder-lot rescan identified further possible buried / former pond risk areas requiring field

confirmation.

On-site: Visible on-site features include a distinct circular water candidate centrally located northeast, a small building and material piles in the southeast quadrant, and cleared earth disturbance around the building area. The water feature shows vegetation around it with a water presence evident in both current and historical imagery. No other obvious water bodies are strictly within the site boundary. Targeted rescan placed greater emphasis on secondary former pond / buried basin risk areas.

Adjacent / context: Adjacent to the site to the east and northeast are natural creeks (Cabbage Tree Creek) and additional pond-like water bodies. There is scattered residential housing to the south and west. The eastern side shows consistent water bodies depicted as ponds in historical and current imagery.

Site Details

Address	502 Church Road, Taigum QLD
Location source	polygon
Latitude / Longitude	-27.333805, 153.048571
Site bbox	267.6 m × 274.6 m
Context bbox	321.6 m × 328.6 m
Polygon supplied	Yes

Key Flags

Key Flag	Level	Comment
Former water features	Elevated	The circular water feature on-site and adjacent ponds are visible through multi-temporal historic imagery from 1995 to present.
Vegetation / land change	Low	Some clearing around disturbed earth and building footprint on site, mostly limited to southeast area.
Fill / disturbance	Moderate	Disturbed soil and material piles seen near small building on eastern side of the site, possible fill or earthworks.

Flag Summary

Potential Fill / Disturbance	**Moderate**
Disturbed soil and material piles seen near small building on eastern side of the site, possible fill or earthworks.	

Former Water Features	**Elevated**

The circular water feature on-site and adjacent ponds are visible through multi-temporal historic imagery from 1995 to present.

Vegetation / Land Change	**Low**
Some clearing around disturbed earth and building footprint on site, mostly limited to southeast area.	

Screening Outcome

The site has a persistent on-site pond and evidence of recent earth disturbance with probable fill. Adjacent natural drainage features nearby. Recommended further ground inspection and targeted geotechnical assessment.

Primary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Pond A	former_pond	on_site	high	A subtle oval depression with darker vegetation tone suggesting a former pond footprint, detected mainly in 1995 historical aerial image, not clearly visible in recent imagery.

Secondary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Disturbance Area	disturbance	on_site	medium	Cleared soil and material piles near small building in southeast quadrant, disturbed earth footprint
Disturbance Area	disturbance	on_site	medium	Area of soil disturbance/earthworks near south side of water feature, visible in 1995 image with lighter tone soil and material piles.

Adjacent Contextual Influences

Feature	Type	Relation	Confidence	Notes
water_feature_2	drainage_feature	on_site	high	Additional water bodies visible adjacent east and northeast of site boundary near natural creek and park

Detailed Findings

Visible Observations

• Circular water feature with vegetation encircling central pond.

• Material and soil disturbance near small building in southeast quadrant of site.

• Natural drainage features and ponds adjacent to site east and northeast.

• Consistent pond presence with vegetation ring

• Minor soil disturbance near pond evident historically

• No clear large-scale drainage channels within site

• Adjacent lands consistent with rural land use

Overall Change Timeline

General: Water feature consistently present from 1995 through 2021 with minor morphology and water condition changes.

General: Disturbance related to building and materials pile appears recent in latest imagery.

1995: Main pond visible with some nearby disturbance

2015: Pond remains, disturbance less pronounced

2021: Pond persists, minor changes to soil surface

Possible Geotechnical Implications

• Former pond signatures may indicate fill, uncontrolled fill, deep fill, soft ground, or moisture-sensitive soils.

Recommended Follow-Up

• Detailed geotechnical investigation is strongly recommended based on identified site history risks.

Supporting Imagery

current_wide_context — current

Source: mapbox_bbox_wide_context

current_context — current

Source: mapbox_bbox_context

current_subzone_nw — current

Source: mapbox_bbox_subzone

current_subzone_west — current

Source: mapbox_bbox_subzone

current_site — current

Source: mapbox_bbox_site

historical_qld_followup_1 — 1995 (1995-06-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | Resolution: 60 2

historical_qld_followup_4 — 2015 (2015-05-30)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2015_10cm_SISP_LGA | Resolution: 10 2

historical_qld_followup_6 — 2021 (2021-07-17)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | Resolution: 10 2

Limitations & Disclaimer

- Limited temporal coverage in mid-years may mask intermittent changes.
- No ground-level or hydrological data to confirm water presence or quality.
- Resolution limits detection of subtle buried or small features
- Seasonal vegetation and soil moisture affect water visibility
- Lack of detailed capture dates for some current subzone images

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.