# AI SITE HISTORY REPORT

502 Church Road, Taigum QLD

Generated 08 Apr 2026 | Lat -27.333805, Lng 153.048571 | Confidence: High

## Executive Summary

Site shows a prominent circular water feature pond near the northeast quadrant, visible throughout historical and current imagery. Some disturbance from cleared areas and potential fill near the southeast side. Adjacent dense vegetation and drainage creek nearby. Additional targeted remainder-lot rescan identified further possible buried / former pond risk areas requiring field confirmation.

**On-site:** One prominent circular water candidate with vegetated edges in the northeast area of the site appears consistently from 1995 to current. A cleared soil/disturbance area with construction debris is visible in the southeast quadrant. Smaller scattered vegetation clumps are also visible within the site. Targeted rescan placed greater emphasis on secondary former pond / buried basin risk areas.

**Adjacent / context:** To the north and northeast is dense vegetation with a creek visible (Cabbage Tree Creek). Residential housing and parkland are directly south. A linear water feature or drainage basin lies immediately east outside the site boundary adjacent to Church Road.

## Site Details

| | |
|---|---|
| **Address** | 502 Church Road, Taigum QLD |
| **Location source** | polygon |
| **Latitude / Longitude** | -27.333805, 153.048571 |
| **Site bbox** | 267.6 m × 274.6 m |
| **Context bbox** | 321.6 m × 328.6 m |
| **Polygon supplied** | Yes |

## Key Flags

| Key Flag | Level | Comment |
|---|---|---|
| **Former water features** | High | Circular pond visible in all imagery from 1995 to current, stable and consistent in location and water presence. |
| **Vegetation / land change** | Moderate | Recent clearing and soil exposure in southeast quadrant, probably related to development or site disturbance. |
| **Fill / disturbance** | Elevated | Fill or scattered materials near the northeast boundary area visible in historical imagery. |

## Flag Summary

| | |
|---|---|
| **Potential Fill / Disturbance** | **Elevated** |
| Fill or scattered materials near the northeast boundary area visible in historical imagery. | |

| | |
|---|---|
| **Former Water Features** | **High** |
| Circular pond visible in all imagery from 1995 to current, stable and consistent in location and water presence. | |

| | |
|---|---|
| **Vegetation / Land Change** | **Moderate** |
| Recent clearing and soil exposure in southeast quadrant, probably related to development or site disturbance. | |

## Screening Outcome

Site includes a persistent water body candidate on-site and some possible fill/disturbance areas to consider. Adjacent natural drainage and vegetation important for site context. Recommended site investigations focused on water body and fill zones.

## Primary On-Site Risks

| Feature | Type | Relation | Confidence | Notes |
|---|---|---|---|---|
| Pond A | former_pond | on_site | high | Prominent circular pond with vegetated edges, visible throughout historical years and present; consistent footprint and water presence. |
| Pond B | former_pond | on_site | high | Prominent circular pond with vegetated edges, consistent water presence visible in 1995 and 2021 imagery. |

## Adjacent Contextual Influences

| Feature | Type | Relation | Confidence | Notes |
|---|---|---|---|---|
| Disturbance Area | disturbance | adjacent | medium | Cleared soil/disturbed area with visible material piles or construction debris near southeast quadrant. |
| drainage_1 | drainage_feature | on_site | medium | Linear elongated water feature (drainage or basin) immediately east along Church Road outside site boundary. |
| Disturbance Area | disturbance | adjacent | medium | Cleared soil and fill-like area with some scattered materials east of the pond near northeast site boundary, clear in 1995 historic imagery. |
| Adjacent Creek | drainage_feature | adjacent | high | Narrow elongated creek with tree-lined banks on eastern adjacent area, identified as Cabbage Tree Creek. |

## Detailed Findings

### Visible Observations

- Stable circular pond in northeast
- Drainage water body just outside eastern boundary
- Cleared/disturbed soil and possible fill area in southeast
- Mature trees scattered, especially adjacent to pond

### Overall Change Timeline

**General:** Circular pond present consistently from 1995 through 2021

**General:** Southeast disturbance and clearing more evident in recent 2019-2021 images

### Possible Geotechnical Implications

• Former pond signatures may indicate fill, uncontrolled fill, deep fill, soft ground, or moisture-sensitive soils.

### Recommended Follow-Up

• Detailed geotechnical investigation is strongly recommended based on identified site history risks.

## Supporting Imagery

**current_wide_context — current**

Source: mapbox_bbox_wide_context

**current_context — current**

Source: mapbox_bbox_context

**current_subzone_nw — current**

Source: mapbox_bbox_subzone

**current_subzone_west — current**

Source: mapbox_bbox_subzone

**current_site — current**

Source: mapbox_bbox_site

**historical_qld_followup_1 — 1995 (1995-06-18)**

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | Resolution: 60 2

**historical_qld_followup_4 — 2015 (2015-05-30)**

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2015_10cm_SISP_LGA | Resolution: 10 2

**historical_qld_followup_6 — 2021 (2021-07-17)**

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | Resolution: 10 2

## Limitations & Disclaimer

- Imagery resolution limits detailed soil or water condition assessments
- Temporal gaps between historical images limit detection of intermittent changes
- Limited resolution of older historical imagery constrains fine detail interpretation.
- Only visual features screened, no subsurface or soil data available.

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.