AI SITE HISTORY REPORT

502 Church Road, Taigum QLD

Generated 08 Apr 2026 | Lat -27.333805, Lng 153.048571 | Confidence: High

Executive Summary

A circular water feature consistent with a pond is located on site in the northeast quadrant. It is visible in all current imagery and clearly present in historical imagery from 1995 onwards. Adjacent to the pond on site is an area of cleared ground with earthworks and what appears to be disturbed soil or fill near a structure. Beyond the site to the northeast is a creek system. There are no large water bodies immediately adjacent except the creek northeast off site. Historical imagery indicates multiple on-site pond features, including secondary or buried pond signatures. Additional targeted remainder-lot rescan identified further possible buried / former pond risk

areas requiring field confirmation.

On-site: One primary circular water candidate feature visible in the northeast part of the site. Disturbance candidates include a cleared area with machinery or material piles near the central east boundary adjacent to Church Rd. Several trees and patches of vegetation surround the pond and scattered around the cleared field. Multiple pond features are present on site, including historical and/or buried pond signatures. Targeted rescan placed greater emphasis on secondary former pond / buried basin risk areas.

Adjacent / context: To the northeast beyond site boundary lies Cabbage Tree Creek, a drainage candidate elongated and shaded by vegetation. To the south and west are residential and parkland areas with no visible water features. An elongated dark water feature is seen off-site adjacent to the east boundary but outside the site.

Site Details

Address	502 Church Road, Taigum QLD
Location source	polygon
Latitude / Longitude	-27.333805, 153.048571
Site bbox	267.6 m × 274.6 m
Context bbox	321.6 m × 328.6 m
Polygon supplied	Yes

Key Flags

Key Flag	Level	Comment
Former water features	High	Circular pond with vegetated ring clearly visible since 1995 on site northeast.
Vegetation / land change	Low	Some clearing and disturbed soil patches visible on site in recent imagery.
Fill / disturbance	Moderate	Evidence of earthworks or soil disturbance especially near buildings in the east-central part of site.

Flag Summary

Potential Fill / Disturbance	**Moderate**
Evidence of earthworks or soil disturbance especially near buildings in the east-central part of site.	
Former Water Features	**High**

Circular pond with vegetated ring clearly visible since 1995 on site northeast.	
Vegetation / Land Change	**Low**
Some clearing and disturbed soil patches visible on site in recent imagery.	

Screening Outcome

Site contains a stable historical pond feature and some localized disturbance; moderate potential risk for geotechnical consideration.

Primary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Pond B	former_pond	on_site	high	Circular pond with vegetated edges visible at northeast area of site. Water is present with some aquatic vegetation and clear historical presence since 1995.
Pond A	former_pond	on_site	high	Circular pond with vegetated edges visible on site northeast. Water present with aquatic vegetation and clear presence since 1995.

Secondary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Disturbance Area	disturbance	on_site	medium	Cleared soil or disturbed ground with material piles or construction debris near center-east of site, adjacent to the pond but separate.
Pond C	pond	on_site	medium	Elongated pond or water body immediately adjacent to east boundary outside site.

Adjacent Contextual Influences

Feature	Type	Relation	Confidence	Notes
Adjacent Creek	drainage_feature	adjacent	high	Cabbage Tree Creek narrow vegetated drainage channel northeast beyond site boundary.
Adjacent Pond 1	pond	adjacent	medium	Elongated pond or water body immediately adjacent to east boundary outside site.

Feature Timeline

water_candidate_1 — 1995:

water_candidate_1 — 2002:

water_candidate_1 — 2005:

water_candidate_1 — 2008:

water_candidate_1 — 2009:

water_candidate_1 — 2021:

Detailed Findings

Visible Observations

- Circular pond with green vegetated boundary.
- Cleared area with material piles near pond.
- Creek drainage line northeast beyond site.
- Small adjacent water body east off site.

Overall Change Timeline

General: Pond stable over time since 1995.

General: Some clearing and disturbance since early 2000s around structures.

Possible Geotechnical Implications

- Former pond signatures may indicate fill, uncontrolled fill, deep fill, soft ground, or moisture-sensitive soils.
- Active pond areas may indicate local wetness influence and moisture variability in surrounding ground.

Recommended Follow-Up

- Detailed geotechnical investigation is strongly recommended based on identified site history risks.

Supporting Imagery

current_wide_context — current

Source: mapbox_bbox_wide_context

current_context — current

Source: mapbox_bbox_context

current_subzone_nw — current

Source: mapbox_bbox_subzone

current_subzone_west — current

Source: mapbox_bbox_subzone

current_site — current

Source: mapbox_bbox_site

historical_qld_followup_1 — 1995 (1995-06-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | Resolution: 60 2

historical_qld_followup_5 — 2009 (2009-09-13)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2009_15cm_SISP_LGA | Resolution: 15 2

historical_qld_followup_8 — 2015 (2015-05-30)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2015_10cm_SISP_LGA | Resolution: 10 2

Limitations & Disclaimer

- Historical imagery resolution limits detection of finer disturbance features.
- No recent capture date metadata available for the current images.
- Historical imagery resolution less clear than current.
- Small or subtle buried ponds might not be visible.

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.