AI SITE HISTORY REPORT

502 Church Road, Taigum QLD

Generated 08 Apr 2026 | Lat -27.333834, Lng 153.048547 | Confidence: High

Executive Summary

The site contains one prominent water feature at the northeast corner, visible consistently across all years from 1995 to 2021. No other distinct waterbodies or substantial disturbances are evident within the site boundary. Additional targeted remainder-lot rescan identified further possible buried / former pond risk areas requiring field confirmation.

On-site: A circular water feature, likely a pond, is located at the northeast part of the site adjacent to Church Rd. The site is predominantly cleared land with some scattered trees and minor earthwork/disturbance near the center-east. Targeted rescan placed greater emphasis on secondary former pond / buried basin risk areas.

Adjacent / context: Adjacent to the site, further west and south, there are residential areas and some additional small water bodies. To the north and northeast there are wooded areas and open fields with no additional identified water bodies or disturbances directly adjacent.

Site Details

Address	502 Church Road, Taigum QLD
Location source	polygon
Latitude / Longitude	-27.333834, 153.048547
Site bbox	141.9 m × 145.4 m
Context bbox	195.9 m × 199.4 m
Polygon supplied	Yes

Key Flags

Key Flag	Level	Comment
Former water features	High	The single circular water body pond is present in all historic imagery dating back to 1995 and shows no significant change in extent.
Vegetation / land change	Low	Some minor vegetation clearing evident around the pond perimeter and in the cleared open field on site; no major clearing detected over time.
Fill / disturbance	Moderate	Possible fill or disturbance area near the center-east of the site evident in current imagery but not identifiable in historic images.

Flag Summary

Potential Fill / Disturbance — Moderate

Possible fill or disturbance area near the center-east of the site evident in current imagery but not identifiable in historic images.

Former Water Features — High

The single circular water body pond is present in all historic imagery dating back to 1995 and shows no significant change in extent.

Vegetation / Land Change	Low
Some minor vegetation clearing evident around the pond perimeter and in the cleared open field on site; no major clearing detected over time.	

Screening Outcome

Site contains stable water feature at northeast and minor disturbance in center-east. Moderate geotechnical risk from water presence and localized fill/disturbance. Site history reasonably stable.

Primary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Pond A	former_pond	on_site	high	Distinct circular pond with vegetated perimeter in northeast corner of the site. Visible in all temporal images, including historical from 1995 to 2021.

Secondary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Disturbance Area	disturbance	on_site	medium	Cleared soil or possible fill material pile near center-east of site with associated bare ground. No distinct water signature.

Adjacent Contextual Influences

Feature	Type	Relation	Confidence	Notes
Adjacent Pond 1	former_pond	adjacent	high	Distinct circular pond with dense vegetation around perimeter, visible in historical 1995 and more recent 2021 imagery at northeast corner of site. Clear and consistent footprint.

Detailed Findings

Visible Observations

• Single circular pond with green vegetated margins on northeast.

• Cleared agricultural/pasture land dominating site.

• Cluster of trees and disturbed soil patches near site center-east.

• Strong circular pond feature with vegetated perimeter northeast corner; surrounding areas largely cleared farmland.

Overall Change Timeline

General: Water body stable since 1995 without major size or morphology changes.

General: Increase in visible surface disturbance around site center-east post-2015.

General: Consistent presence of the northeast pond feature from 1995 to 2021 with minimal visible change in morphology.

Possible Geotechnical Implications

• Former pond signatures may indicate fill, uncontrolled fill, deep fill, soft ground, or moisture-sensitive soils.

Recommended Follow-Up

• Detailed geotechnical investigation is strongly recommended based on identified site history risks.

Supporting Imagery

current_wide_context — current

Source: mapbox_bbox_wide_context

current_context — current

Source: mapbox_bbox_context

current_subzone_nw — current

Source: mapbox_bbox_subzone

current_subzone_west — current

Source: mapbox_bbox_subzone

current_site — current

Source: mapbox_bbox_site

historical_qld_followup_1 — 1995 (1995-06-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | Resolution: 60 2

historical_qld_followup_4 — 2015 (2015-05-30)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2015_10cm_SISP_LGA | Resolution: 10 2

historical_qld_followup_6 — 2021 (2021-07-17)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | Resolution: 10 2

Limitations & Disclaimer

- Limited image resolution may obscure smaller features.
- No access to sub-surface or soil data to confirm fill or contamination.
- Temporal image coverage gaps may miss minor transient features.
- Historical images older and lower resolution, some subtle features may be missed.
- No temporal images between 1995 and 2021 analyzed beyond those provided.

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.