AI SITE HISTORY REPORT

502 Church Road, Taigum QLD

Generated 08 Apr 2026 | Lat -27.333834, Lng 153.048547 | Confidence: Medium

Executive Summary

The site at 502 Church Road, Taigum QLD shows a clear presence of a former pond or dam feature in the northeast corner near Church Rd. This water feature persists in historical imagery over multiple decades but is no longer visibly water filled in the latest images, indicating possible infilling or drying. There is visible earth disturbance and some vegetation clearing around the site, particularly near the central and southeastern parts where buildings and material piles exist. Additional targeted remainder-lot rescan identified further possible buried / former pond risk areas requiring field confirmation.

On-site: One prominent water candidate feature is located northeast on-site near Church Road, historically visible as a pond or dam lined with vegetation. Earthworks and disturbance are visible near the central and southeast parts of the site associated with structures and cleared land. Targeted rescan placed greater emphasis on secondary former pond / buried basin risk areas.

Adjacent / context: Adjacent land, particularly to the east and southeast, contains large water bodies or ponds that are visible consistently in historical images. Residential areas lie to the south, and the northern parts feature mixed vegetation and grassland.

Site Details

Address	502 Church Road, Taigum QLD
Location source	polygon
Latitude / Longitude	-27.333834, 153.048547
Site bbox	141.9 m × 145.4 m
Context bbox	195.9 m × 199.4 m
Polygon supplied	Yes

Key Flags

Key Flag	Level	Comment
Former water features	High	The pond/dam near the northeast boundary is evident from 1995 through 2019 historical images but is less visible or dry in the current imagery.
Vegetation / land change	Moderate	Central and southeast parts of the site show areas of cleared terrain with little to no vegetation.
Fill / disturbance	Elevated	Presence of material piles and earth disturbance near buildings indicates likely fill or construction disturbance.

Flag Summary

Potential Fill / Disturbance — **Elevated**

Presence of material piles and earth disturbance near buildings indicates likely fill or construction disturbance.

Former Water Features — **High**

The pond/dam near the northeast boundary is evident from 1995 through 2019 historical images but is less visible or dry in the current imagery.

Vegetation / Land Change	**Moderate**
Central and southeast parts of the site show areas of cleared terrain with little to no vegetation.	

Screening Outcome

Site evidences a historical water feature with current absence of visible water and moderate earth disturbance. Further geotechnical investigation is warranted focused on former pond and disturbance zones.

Primary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Pond A	former_pond	on_site	high	Distinct circular pond or dam visible along northeast boundary near Church Road. Water present historically in several years, less visible or dry in the current images.

Secondary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Disturbance Area	disturbance	on_site	medium	Cleared earth areas and material piles near center and southeast part of site with building structures visible.

Detailed Findings

Visible Observations

• Circular pond/dam footprint with vegetation in northeast site corner

• Cleared earth and rubble piles in center-southeast parts

• Sparse trees scattered mostly around pond perimeter and site boundary

Overall Change Timeline

1995-2019: Pond clearly visible with water

2021: Pond area appears dry or infilled, reduced visible water extent

General: Increasing earth disturbance around central buildings observed in latest imagery

Possible Geotechnical Implications

• Former pond signatures may indicate fill, uncontrolled fill, deep fill, soft ground, or moisture-sensitive soils.

Recommended Follow-Up

• Detailed geotechnical investigation is strongly recommended based on identified site history risks.

Supporting Imagery

current_wide_context — current

Source: mapbox_bbox_wide_context

current_context — current

Source: mapbox_bbox_context

current_subzone_nw — current

Source: mapbox_bbox_subzone

current_subzone_west — current

Source: mapbox_bbox_subzone

current_site — current

Source: mapbox_bbox_site

historical_qld_followup_1 — 1995 (1995-06-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | Resolution: 60 2

historical_qld_followup_4 — 2015 (2015-05-30)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2015_10cm_SISP_LGA | Resolution: 10 2

historical_qld_followup_6 — 2021 (2021-07-17)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | Resolution: 10 2

Limitations & Disclaimer

- Recent images have medium resolution affecting detail clarity
- No capture date for current images limits precise temporal comparison
- No subsurface data to confirm pond infill extent or soil condition
- AI output parsing failed. Manual review required.

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.