AI SITE HISTORY REPORT

502 Church Road, Taigum QLD

Generated 08 Apr 2026 | Lat -27.333834, Lng 153.048547 | Confidence: Medium

Executive Summary

The site and adjacent context contain multiple circular and irregular water bodies visible in historical and current aerial imagery, with some changes over time. There is evidence of past water features that have either diminished or been infilled or disturbed. Additional targeted remainder-lot rescan identified further possible buried / former pond risk areas requiring field confirmation. Additional targeted remainder-lot rescan identified further possible buried / former pond risk areas requiring field confirmation.

On-site: On site, there is a distinct circular vegetated waterbody feature near the northeast corner visible in current imagery with water presence. The site shows cleared land with some disturbances possibly linked to fill or construction but no clear current open water within the site's main square area. Targeted rescan placed greater emphasis on secondary former pond / buried basin risk areas. Targeted rescan placed greater emphasis on secondary former pond / buried basin risk areas.

Adjacent / context: Immediately adjacent to the north and northeast of the site, there are several significant, large, vegetated ponds visible consistently in historical and current imagery. These nearby water bodies have well-defined outlines and wet vegetation, likely maintained or natural ponds.

Site Details

Address	502 Church Road, Taigum QLD
Location source	polygon
Latitude / Longitude	-27.333834, 153.048547
Site bbox	141.9 m × 145.4 m
Context bbox	195.9 m × 199.4 m
Polygon supplied	Yes

Key Flags

Key Flag	Level	Comment
Former water features	Elevated	Circular vegetated waterbody on site present historically and currently suggests long-standing former pond; adjacent ponds have been persistent and stable.
Vegetation / land change	Low	Some clearing and disturbed soil seen in current site imagery mainly around center-southern portion.
Fill / disturbance	Moderate	Disturbance candidate with debris piles and cleared land suggests possible fill or earthworks recently.

Flag Summary

Potential Fill / Disturbance	**Moderate**
Disturbance candidate with debris piles and cleared land suggests possible fill or earthworks recently.	

Former Water Features	**Elevated**
Circular vegetated waterbody on site present historically and currently suggests long-standing former pond; adjacent ponds have been persistent and stable.	

Vegetation / Land Change	Low
Some clearing and disturbed soil seen in current site imagery mainly around center-southern portion.	

Screening Outcome

Site contains persistent and likely long-standing vegetated water feature with nearby large ponds; there is moderate recent disturbance inside the site that warrants further investigation for possible fill or stability risks.

Primary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Pond D	former_pond	on_site	medium	Faint, irregular, partially vegetated basin signature detected in 1995 imagery near south-central zone; no clear water visible in recent images.
Pond A	former_pond	on_site	high	Large circular vegetated waterbody near northeast edge of site visible in 1995 imagery with dark water interior and green vegetated ring.
Pond C	former_pond	on_site	medium	Faint irregular basin signature, partially vegetated, visible in 1995 imagery near south-central site zone; no clear water in 2021 images.

Secondary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Pond B	pond	on_site	medium	Circular vegetated waterbody visible near northeast edge of site boundary, partly filled vegetation, water or wet soils seen.
Disturbance Area	disturbance	on_site	medium	Cleared earth and disturbed area with debris piles visible in site center-south, no visible water signature.

Adjacent Contextual Influences

Feature	Type	Relation	Confidence	Notes
Adjacent Pond 2	pond	adjacent	high	Smaller oval pond directly north-adjacent and visible historically and in recent images, partially vegetated and muddy areas.
Adjacent Pond 1	pond	adjacent	high	Distinct circular vegetated waterbody with visible water or wet soils near northeast site boundary, consistent presence from 1995 to 2021.

Disturbance Area	disturbance	adjacent	medium	Small cleared soil and possible fill area near central south zone with construction materials and disturbed patches in recent imagery.

Detailed Findings

Visible Observations

• Circular dense vegetation indicative of former or current pond on site northeastern corner

• Multiple larger ponds adjacent to site northeast visible through all times

• Cleared land and debris piles in site southern central area

• Large circular vegetated pond consistent across years northeast site edge

• Secondary faint basin visible only in older imagery

• Recent fill and soil disturbance in central-southeast portion

• Northeast circular pond partly filled with vegetation in 1995

• South-central irregular depression faintly visible in 1995 imagery

• No clear water presence in 2021 imagery

• Buildings and maintained grassed areas prevalent in the site

Overall Change Timeline

General: Pond features adjacent to site remain stable from 1995 to 2021

General: On site circular vegetated pond feature consistent historically and current

General: Site central area recently disturbed with clearing and material piles present

General: Primary pond stable in shape and extent from 1995 to 2021

General: Secondary basin signature disappeared in recent imagery

General: Fill/disturbance appears more recent (2021) in central-southeast

1995: Two water candidates visible (one large vegetated pond, one faint basin)

2021: Both water features absent or dry, site appears grassed and maintained

Possible Geotechnical Implications

• Active pond areas may indicate local wetness influence and moisture variability in surrounding ground.

• Former pond signatures may indicate fill, uncontrolled fill, deep fill, soft ground, or moisture-sensitive soils.

Recommended Follow-Up

• Detailed geotechnical investigation is strongly recommended based on identified site history risks.

Supporting Imagery

current_wide_context — current

Source: mapbox_bbox_wide_context

current_context — current

Source: mapbox_bbox_context

current_subzone_nw — current

Source: mapbox_bbox_subzone

current_subzone_west — current

Source: mapbox_bbox_subzone

current_site — current

Source: mapbox_bbox_site

historical_qld_followup_1 — 1995 (1995-06-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | Resolution: 60 2

historical_qld_followup_4 — 2015 (2015-05-30)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2015_10cm_SISP_LGA | Resolution: 10 2

historical_qld_followup_6 — 2021 (2021-07-17)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | Resolution: 10 2

Limitations & Disclaimer

- Limited resolution of older historical images restricts precise feature boundary delineation
- No direct subsurface or hydrological data available from imagery alone
- Limited resolution and color quality of historical imagery constrain detection of faint features
- No temporal coverage between 1995 and 2021 to observe intermediate changes
- Historic imagery resolution and quality limits precise boundary delineation
- Recent imagery is high quality but does not indicate subsurface conditions
- No direct geotechnical or hydrological data review provided

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.