AI SITE HISTORY REPORT

502 Church Road, Taigum QLD

Generated 08 Apr 2026 | Lat -27.333834, Lng 153.048547 | Confidence: High

Executive Summary

Current water bodies are visible on-site, and historical imagery also indicates 1 former pond feature or infilled depressions on-site. Site disturbance or possible fill-related ground modification is also visible.

On-site: 2 current on-site pond features are visible in the final interpretation. Disturbance or possible fill-related ground modification is also visible on-site.

Adjacent / context: No significant adjacent water features were carried through the final interpretation.

Site Details

Address	502 Church Road, Taigum QLD
Location source	polygon
Latitude / Longitude	-27.333834, 153.048547
Site bbox	141.9 m × 145.4 m
Context bbox	195.9 m × 199.4 m
Polygon supplied	Yes

Key Flags

Key Flag	Level	Comment
Former water features	High	Oval waterbody visible consistently from 1995 to 2021 with vegetation changes but always appearing as a pond/dam.
Vegetation / land change	Low	Some minor clearing or disturbances within the site center observed in recent imagery.
Fill / disturbance	Moderate	Earthworks or fill visible near center of site but extent and origin uncertain.

Flag Summary

Potential Fill / Disturbance	**Moderate**
Earthworks or fill visible near center of site but extent and origin uncertain.	

Former Water Features	**High**
Oval waterbody visible consistently from 1995 to 2021 with vegetation changes but always appearing as a pond/dam.	

Vegetation / Land Change	**Low**
Some minor clearing or disturbances within the site center observed in recent imagery.	

Screening Outcome

Current on-site water features are present and should be considered in geotechnical assessment. Detailed geotechnical investigation is strongly recommended.

Primary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Pond A	former_pond	on_site	low	Faint large circular vegetated depression outside east-northeast boundary visible in 2021, possibly a seasonal wetland or former pond but uncertain.

Secondary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Pond B	pond	on_site	high	Oval shaped pond/dam with visible water and surrounding vegetation in all historical images including 1995, 2015 and 2021; slightly varying water extent and vegetative cover over time.
Pond C	pond	on_site	high	Oval-shaped pond with consistent water and vegetation signatures visible in 1995 and 2021 images; located central to site by buildings and driveway.
Disturbance Area	disturbance	on_site	medium	Cleared earth and possible material piles or soil disturbance near center of site visible in recent images.

Detailed Findings

Visible Observations

• Historical imagery indicates former on-site pond / wet depression signatures that are not clearly visible as current open water.

• Current imagery shows on-site open water or pond morphology.

• Current imagery shows on-site disturbance or possible fill-related ground modification.

• Clear oval pond/dam with vegetated edge located in northeast quadrant of site.

• Earthen disturbance and material piles near southern-central site area.

• Stable main pond/dam feature onsite with visible water across all years

• No secondary water bodies onsite detected

• Faint vegetated circular patch adjacent northeast of site may warrant contextual attention

• Minor cleared soil and driveway areas evident

Overall Change Timeline

1995-2021: Pond present continuously with fluctuations in visible water extent and vegetation.

2021: Visible earth disturbance at site center increases.

1995-2021: Main pond stable, water extent and vegetation slightly varied

General: No significant earth works or pond removals visible

Possible Geotechnical Implications

• Historical pond or wet depression signatures may indicate fill, uncontrolled fill, deep fill, soft ground, or moisture-sensitive soils.

• Current pond areas may indicate local wetness influence and moisture variability in surrounding ground.

• Disturbance or possible fill areas may indicate variable near-surface conditions and localised compaction variability.

• Active pond areas may indicate local wetness influence and moisture variability in surrounding ground.

• Former pond signatures may indicate fill, uncontrolled fill, deep fill, soft ground, or moisture-sensitive soils.

Recommended Follow-Up

• Detailed geotechnical investigation is strongly recommended based on identified site history risks.

Supporting Imagery

current_wide_context — current

Source: mapbox_bbox_wide_context

current_context — current

Source: mapbox_bbox_context

current_subzone_nw — current

Source: mapbox_bbox_subzone

current_subzone_west — current

Source: mapbox_bbox_subzone

current_site — current

Source: mapbox_bbox_site

historical_qld_followup_1 — 1995 (1995-06-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | Resolution: 60 2

historical_qld_followup_4 — 2015 (2015-05-30)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2015_10cm_SISP_LGA | Resolution: 10 2

historical_qld_followup_6 — 2021 (2021-07-17)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | Resolution: 10 2

Limitations & Disclaimer

- Medium resolution images limit precise delineation of small features.
- No detailed hydrological data to confirm connectivity or infiltration.
- Limited temporal intervals restrict detection of short-term changes.
- AI output parsing failed. Manual review required.
- Resolution limits detection of small or subtle water features
- Single historical and recent year imagery limits temporal change detail
- Subtle infilled or buried features may not be visually detectable

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.