AI SITE HISTORY REPORT

502 Church Road, Taigum QLD

Generated 08 Apr 2026 | Lat -27.333834, Lng 153.048547 | Confidence: High

Executive Summary

One primary water candidate visible as a semi-circular waterbody in the northern sector of the site, present across historical and current imagery. Several disturbance candidates within the site near structures. No clear drainage lines identified on site.

On-site: A semi-circular water feature with vegetation surrounds is visible in the northern part of the property boundary, sustained from 1995 to current. Within the site, cleared areas and material piles are observable near

existing buildings indicating disturbance.

Adjacent / context: Adjacent lands to the north and east show larger semi-circular and oval waterbodies with dense vegetation, possibly managed farm ponds or dams. Residential area to south and west with no visible water features.

Site Details

Address	502 Church Road, Taigum QLD
Location source	polygon
Latitude / Longitude	-27.333834, 153.048547
Site bbox	141.9 m × 145.4 m
Context bbox	195.9 m × 199.4 m
Polygon supplied	Yes

Key Flags

Key Flag	Level	Comment
Former water features	High	The semi-circular water feature is consistently visible from 1995 to present, indicating a long-term waterbody or dam.
Vegetation / land change	Low	Localized clearing and soil disturbance near structures but no large scale vegetation clearing is observed across the site.
Fill / disturbance	Moderate	Some soil disturbance and material piles visible possibly related to site works or storage near buildings.

Flag Summary

Potential Fill / Disturbance — Moderate

Some soil disturbance and material piles visible possibly related to site works or storage near buildings.

Former Water Features — High

The semi-circular water feature is consistently visible from 1995 to present, indicating a long-term waterbody or dam.

Vegetation / Land Change — Low

Localized clearing and soil disturbance near structures but no large scale vegetation clearing is observed across the site.

Screening Outcome

Presence of a historic and current waterbody on site with some evidence of localized disturbance around structures; no drainage lines detected.

Primary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Pond A	former_pond	on_site	high	Faint irregular damp patch or small basin south/southwest of main pond visible only in 1995. May indicate seasonal wetness or minor former pond footprint.

Secondary On-Site Risks

Feature	Type	Relation	Confidence	Notes
	pond	on_site	high	Semi-circular waterbody with vegetated rim evident consistently from 1995 through current timeframe. Visible water or wet area in most aerials.
Disturbance Area	disturbance	on_site	medium	Cleared soil and material piles near structures in central southern sector of the site showing soil disturbance.
	pond	on_site	high	Semi-circular pond with dense vegetated rim and visible water or wet area inside it. Consistent visibility in 1995, 2015, and 2021 images.
	pond	on_site	low	Faint irregular damp patch or small basin visible south or southwest of the main pond in some images; uncertain if permanent water or seasonal wetness.

Detailed Findings

Visible Observations

- Semi-circular water feature with vegetation presence robust across time
- Disturbed soil and material piles near buildings
- No visible drainage or creek features within site boundaries
- Main pond with dense vegetation rim is a dominant water feature
- Smaller damp/faint basin southwest of main feature is subtle and partially vegetated
- Main pond unchanged in visible aerial water footprint across all years.
- Secondary water features visible mainly in 1995 imagery, less distinct or absent later.
- No clear creek or drainage identified on or adjacent site.

Overall Change Timeline

General: Water candidate consistent presence from 1995 to 2021

General: Disturbance areas near structures apparent only in recent imagery from 2015 onwards

General: Main pond stable from 1995 to 2021

General: No significant visible changes to main pond footprint over time

1995: Main pond, secondary smaller pond with water, and faint damp basin all visible.

2015: Main pond visible with water, secondary ponds less distinct or absent.

2021: Main pond still present with water. No secondary ponds clearly visible.

Possible Geotechnical Implications

• Active pond areas may indicate local wetness influence and moisture variability in surrounding ground.

Recommended Follow-Up

• Detailed geotechnical investigation is strongly recommended based on identified site history risks.

Supporting Imagery

current_wide_context — current

Source: mapbox_bbox_wide_context

current_context — current

Source: mapbox_bbox_context

current_subzone_nw — current

Source: mapbox_bbox_subzone

current_subzone_west — current

Source: mapbox_bbox_subzone

current_site — current

Source: mapbox_bbox_site

historical_qld_followup_1 — 1995 (1995-06-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | Resolution: 60 2

historical_qld_followup_4 — 2015 (2015-05-30)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2015_10cm_SISP_LGA | Resolution: 10 2

historical_qld_followup_6 — 2021 (2021-07-17)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | Resolution: 10 2

Limitations & Disclaimer

- No seasonal or hydrologic variation assessment possible from single-date annual imagery
- Some historical imagery lower resolution limiting feature detail accuracy
- Limited resolution in older imagery restricts detection of smaller or subtle water features
- Faint secondary features could not be definitively classified without ground verification
- Historic imagery resolution limits detection confidence for faint or infilled features.
- Seasonal variations may affect visible water presence in some years.

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.