AI SITE HISTORY REPORT

502 Church Road, Taigum QLD

Generated 08 Apr 2026 | Lat -27.333834, Lng 153.048547 | Confidence: High

Executive Summary

Site at 502 Church Road, Taigum QLD shows a distinct former water body visible historically from 1995 through to 2019 with a circular to irregular vegetated depression north-east of central structures. Current imagery shows no visible open water but a prominent formerly pond-like landform with woody vegetation and a cleared central area with scattered debris.

On-site: Within site boundaries, a major candidate water feature visible historically and vegetated currently in the northern and north-eastern part of the site. The central cleared area contains some disturbance with scattered material/earthworks. No current open water detected.

Adjacent / context: Adjacent areas to the east and north display open grassland and wooded areas without visible surface water bodies or disturbances impacting the site footprint.

Site Details

Address	502 Church Road, Taigum QLD
Location source	polygon
Latitude / Longitude	-27.333834, 153.048547
Site bbox	141.9 m × 145.4 m
Context bbox	195.9 m × 199.4 m
Polygon supplied	Yes

Key Flags

Key Flag	Level	Comment
Former water features	High	Clear historical water presence visible as pond from 1995 to 2019. Transitioned to vegetated and partially infilled landform by current imagery.
Vegetation / land change	Low	Central cleared disturbed area associated with current construction or materials.
Fill / disturbance	Moderate	Disturbed soil and debris piles in current imagery within site.

Flag Summary

Potential Fill / Disturbance	Moderate
Disturbed soil and debris piles in current imagery within site.	
Former Water Features	High
Clear historical water presence visible as pond from 1995 to 2019. Transitioned to vegetated and partially infilled landform by current imagery.	
Vegetation / Land Change	Low

Central cleared disturbed area associated with current construction or materials.

Screening Outcome

Site contains a strong candidate former pond that has been infilled/vegetated with minor recent disturbance. Further investigation is recommended due to potential geotechnical risk.

Primary On-Site Risks

Feature	Type	Relation	Confidence	Notes
	former_pond	on_site	high	Prominent vegetated circular to irregular former pond visible from 1995, 2005, 2011, 2015, 2019 imagery. No open water visible in current (2021) images, replaced by vegetation and possible infill.
Pond A	former_pond	on_site	medium	Smaller elongated water patch to north-east of main pond clearly visible in 1995 but not in 2021, showing water and vegetated margins. Absent in recent imagery but historical water presence evident.
Pond B	former_pond	on_site	high	Large irregular, circular shaped water body with vegetated edges visible in 1995 imagery with clear water surface. Visible from multiple 1995 images.

Secondary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Disturbance Area	disturbance	on_site	medium	Cleared disturbed area with scattered debris and disturbed soil near center of site, east side. No visible water. Present in current images only.

Detailed Findings

Visible Observations

- Former pond is well vegetated now with no obvious standing water.
- Central site area shows earthworks and scattered debris piles.
- 1995 imagery shows two water features, 2021 shows no visible water but vegetated depression
- Buildings and minor cleared areas visible
- Site appears stable in recent imagery

Overall Change Timeline

1995-2019: standing water pond present.

2019-2021: pond vegetation increased; water absent; earthworks introduced nearby.

General: 1995 water features present

General: 2021 former ponds dry or infilled/vegetated with no water visible

Possible Geotechnical Implications

• Former pond signatures may indicate fill, uncontrolled fill, deep fill, soft ground, or moisture-sensitive soils.

Recommended Follow-Up

• Detailed geotechnical investigation is strongly recommended based on identified site history risks.

Supporting Imagery

current_wide_context — current

Source: mapbox_bbox_wide_context

current_context — current

Source: mapbox_bbox_context

current_subzone_nw — current

Source: mapbox_bbox_subzone

current_subzone_west — current

Source: mapbox_bbox_subzone

current_site — current

Source: mapbox_bbox_site

historical_qld_followup_1 — 1995 (1995-06-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | Resolution: 60 cm

historical_qld_followup_4 — 2015 (2015-05-30)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2015_10cm_SISP_LGA | Resolution: 10 cm

historical_qld_followup_6 — 2021 (2021-07-17)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | Resolution: 10 cm

Limitations & Disclaimer

- No exact capture dates for current imagery.
- Medium resolution limits detection of small water patches or thin drainage lines.
- AI output parsing failed. Manual review required.
- Single recent and older imagery years only; intermediate years not available
- Imagery resolution limited for detailed boundary mapping

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.