AI SITE HISTORY REPORT

502 Church Road, Taigum QLD

Generated 08 Apr 2026 | Lat -27.333834, Lng 153.048547 | Confidence: Medium

Executive Summary

A current pond is present on-site. Historical imagery also indicates at least one additional former or altered pond / wet depression on-site. Site disturbance or possible fill-related ground modification is also visible. Adjacent off-site water features were identified and treated as contextual only.

On-site: 1 current on-site pond feature is present in the final interpretation. Disturbance or possible fill-related ground modification is also visible on-site.

Adjacent / context: 3 adjacent water features were identified outside the site boundary and treated as contextual only.

Site Details

Address	502 Church Road, Taigum QLD
Location source	polygon
Latitude / Longitude	-27.333834, 153.048547
Site bbox	141.9 m × 145.4 m
Context bbox	195.9 m × 199.4 m
Polygon supplied	Yes

Key Flags

Key Flag	Level	Comment
Former water features	Elevated	Circular pond adjacent to site boundary consistently visible with water presence in multiple historical images; smaller irregular water body partially infilled.
Vegetation / land change	Low	Small disturbed areas and cleared soil patches on-site, with some vegetation maintained on site.
Fill / disturbance	Moderate	Visible debris and disturbed soil footprint on eastern site portion.

Flag Summary

Potential Fill / Disturbance	**Moderate**
Visible debris and disturbed soil footprint on eastern site portion.	
Former Water Features	**Elevated**
Circular pond adjacent to site boundary consistently visible with water presence in multiple historical images; smaller irregular water body partially infilled.	
Vegetation / Land Change	**Low**
Small disturbed areas and cleared soil patches on-site, with some vegetation maintained on site.	

Screening Outcome

A current pond is present on-site and historical imagery also indicates at least one additional former or altered pond / wet depression. Detailed geotechnical investigation is strongly recommended.

Primary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Pond A	former_pond	on_site	high	Circular pond with dense vegetation ring visible adjacent to eastern site boundary, consistently present in historical and current imagery.

Secondary On-Site Risks

Feature	Type	Relation	Confidence	Notes
Pond B	pond	on_site	high	Circular pond with dense vegetation ring visible adjacent to eastern site boundary, clear water signature in historical and current images.
Disturbance Area	disturbance	on_site	medium	Cleared soil, pile of debris/materials and disturbed ground visible in central eastern site area.

Adjacent Contextual Influences

Feature	Type	Relation	Confidence	Notes
Adjacent Pond 1	former_pond	adjacent	low	Small dark circular patch near northern edge of property in 1995 imagery, possible small pond or wet depression not visible in later imagery.
Adjacent Pond 2	pond	adjacent	high	Circular pond with dense vegetation ring adjacent to eastern site boundary, visible in 1995, 2015 historical images and current aerial imagery.
Adjacent Pond 3	former_pond	adjacent	medium	Irregular-shaped, partially vegetated former water feature or pond detected south of the main pond in 1995 imagery only, less distinct in later years.

Detailed Findings

Visible Observations

- Circular vegetated pond on adjacent lot eastern side
- Disturbed soil and debris on eastern part of site
- No on-site obvious water bodies

Overall Change Timeline

General: 1995-2015 pond consistently visible with slight changes in fill or vegetation

General: On-site disturbance apparent only in recent current image

Possible Geotechnical Implications

- Active pond areas may indicate local wetness influence and moisture variability in surrounding ground.
- Former pond signatures may indicate fill, uncontrolled fill, deep fill, soft ground, or moisture-sensitive soils.

Recommended Follow-Up

- Detailed geotechnical investigation is strongly recommended based on identified site history risks.

Supporting Imagery

current_wide_context — current

Source: mapbox_bbox_wide_context

current_context — current

Source: mapbox_bbox_context

current_subzone_nw — current

Source: mapbox_bbox_subzone

current_subzone_west — current

Source: mapbox_bbox_subzone

current_site — current

Source: mapbox_bbox_site

historical_qld_followup_1 — 1995 (1995-06-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | Resolution: 60 cm

historical_qld_followup_5 — 2009 (2009-09-13)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2009_15cm_SISP_LGA | Resolution: 15 cm

historical_qld_followup_8 — 2015 (2015-05-30)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2015_10cm_SISP_LGA | Resolution: 10 cm

Limitations & Disclaimer

- Limited to aerial imagery without ground truth
- Historical imagery resolution and seasonal effects may affect water visibility
- Lower resolution and color quality in historical imagery limits detection of smaller or subtle features.
- No recent high-resolution imagery beyond 2021 to confirm current states.
- Imagery resolution limits confidence for smaller or faint water features.
- Only select years of imagery available for temporal comparison.

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.