AI SITE HISTORY REPORT

502 Church Road, Taigum QLD 4018

Generated 07 Apr 2026 | Lat -27.333162, Lng 153.048970 | Confidence: High

Executive Summary

The site at 502 Church Road, Taigum QLD 4018 contains one distinct pond within the lot boundary, visible from 1995 through current imagery, with no evidence of significant shrinking or filling. Vegetation clearing on-site is moderate to major over time, with no clear signs of engineered fill or major disturbance on the lot.

Potential Fill / Disturbance	Low
No visible fill, engineered pads, or major earthworks apparent inside lot boundary.	

Former Water Features	Elevated
One consistent circular pond feature visible within lot from 1995 to present, with unchanged size suggesting persistence.	

Vegetation / Land Change	Elevated
Vegetation shows clear reduction over time, with largely cleared areas present in latest imagery compared to dense vegetation historically.	

Screening Outcome

Site contains a stable, likely natural or long-standing pond within boundaries with significant vegetation changes but no evidence of engineered fill. Further detailed geotechnical assessment recommended focusing on pond influence and soil moisture.

Detailed Findings

Visible Observations

• One circular pond water feature visible wholly within lot boundary from 1995 to current imagery.

• Vegetation around pond varies over time with a more open cleared area around the pond in current imagery compared to denser vegetation in earlier years.

• No visible cut/fill benches, engineered building pads, or imported fill evident within lot boundary.

• No visible prior structures or demolition debris on site.

• Surrounding area includes dirt tracks and other vegetation outside lot boundary.

Change Timeline

1995: Circular pond fully visible with open water and aquatic vegetation around edges; dense surrounding vegetation on-site.

2007: Pond remains fully visible, water presence confirmed; vegetation shows some reduction near pond edges.

2013: Pond still clearly visible with similar size and shape; some open soil or clearing around pond boundary inside lot.

2018: Pond maintains presence and size; vegetation clearing on-site increases especially around pond periphery.

2021/current: Pond still visible with water or wet soil signature; major vegetation clearing around pond site within lot boundary.

Possible Geotechnical Implications

• Presence of an on-site persistent pond may indicate higher water table or localized saturation affecting foundations.

• Vegetation clearing suggests prior disturbance which may alter soil conditions near pond edges.

• No clear indications of engineered fill, but pond and surrounding soil moisture conditions require further investigation.

Recommended Follow-Up

• Conduct geotechnical borehole drilling near pond and cleared areas to assess subsurface moisture and soil profile.

• Evaluate water table elevations and drainage patterns relative to pond location.

• Perform soil sampling for potential weak zones or organic material near pond margins.

• Investigate historical land use records for any undocumented disturbance or modifications.

Supporting Imagery

current_site — current

Source: mapbox_bbox_site

historical_qld_followup_1 — 1995 (1995-06-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543

historical_qld_followup_2 — 2007 (2007-04-16)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2007_15cm_SISP_LGA

historical_qld_followup_3 — 2013 (2013-09-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2013_10cm_SISP_LGA

Limitations & Disclaimer

- Imagery resolution and angle limit detailed interpretation of subtle earthworks.
- Water presence interpretation constrained by seasonality and image capture timing.
- No subsurface information available; interpretations based solely on visible surface features.

This AI site history scan is a preliminary screening tool only. It should be used to identify possible indicators for further professional review, not as a substitute for geotechnical investigation or engineering design.