AI SITE HISTORY REPORT

502 Church Road, Taigum QLD 4018

Generated 07 Apr 2026 | Lat -27.333190, Lng 153.049000 | Confidence: High

Executive Summary

The site at 502 Church Road, Taigum QLD 4018 contains a single distinct circular pond centrally located on-site, which has persisted over the observed years (1994-2022) with some fluctuations in water coverage. The surrounding land appears mostly undisturbed with minor clearing and no significant fill or disturbance visible on-site. Adjacent context shows a larger watercourse (Cabbage Tree Creek) northeast of the lot. No other ponds or dams are evident within the site boundary.

On-site: One circular pond is located centrally on-site and has been a persistent feature from 1994 through 2022, with water presence most years but some drying or reduced water coverage visible in certain years. Surrounding land is largely open with grass and sparse trees; there is a small cleared area and some structures/buildings south of the pond. No evidence of recent fill or large-scale earthworks on-site.

Adjacent / context: Cabbage Tree Creek lies adjacent to the northeast boundary offering natural drainage context. To the east of the site is a highway corridor with no direct hydrological features on-site. Residences and cleared parks are located to the south beyond the site boundary.

Site Details

Address	502 Church Road, Taigum QLD 4018
Location source	user_supplied_coordinates
Latitude / Longitude	-27.333190, 153.049000
Site bbox	180.0 m × 180.0 m
Context bbox	270.0 m × 270.0 m
Polygon supplied	No

Key Flags

Key Flag	Level	Comment
Former water features	Low	No evidence of additional former ponds or dams within site boundary
Vegetation / land change	Low	Some minor clearing around structures south of pond but no major clearing on-site
Fill / disturbance	Low	No visible fill or significant disturbance inside the site across years

Flag Summary

Potential Fill / Disturbance	Low
No visible fill or significant disturbance inside the site across years	
Former Water Features	Low
No evidence of additional former ponds or dams within site boundary	
Vegetation / Land Change	Low

Some minor clearing around structures south of pond but no major clearing on-site

Screening Outcome

The site contains a persistent central pond with stable extent over decades and minor surrounding clearing, without evidence of major filling or disturbance. Geotechnical risk related to pond soils should be further assessed in detailed investigations.

Distinct Feature Review

Feature	Type	Relation	Status	Notes
Pond A	pond	on_site	persistent	Circular pond centrally located within site, water present most years, surrounded by natural vegetation and minor cleared area

Feature Timeline

Pond A — 1994: Pond visible with water, surrounded by trees and grass

Pond A — 2007: Water extent similar, possibly reduced compared to 1994

Pond A — 2013: Pond water level reduced and vegetation denser on embankment

Pond A — 2018: Water coverage increased, surrounding land unchanged

Pond A — 2022: Water present, pond edges stable with no signs of disturbance or filling

Detailed Findings

Visible Observations

• Single circular pond feature on-site, centrally located

• Pond water visible in most historical and recent imagery with varying extent

• Minor clearing and grassy open areas surrounding the pond

• Small cluster of structures south of the pond within site

• No distinct second pond or dam visible on-site

• Cabbage Tree Creek adjacent northeast with dense riparian vegetation

• Highway infrastructure east of site boundary with no visible water features

Overall Change Timeline

1994-2007: Pond present with water, with some adjacent vegetation; little visible land disturbance

2007-2013: Pond water level or coverage may have reduced slightly; vegetation matured surrounding pond

2013-2018: Pond water coverage increased again; minor surface disturbance south of pond appeared

2018-2022: Pond water mostly persistent; no new major land clearing or fill observed on-site

Possible Geotechnical Implications

• Presence of a persistent pond on-site may indicate local groundwater or soil moisture variability

• Potential for soft, water-affected soils near the pond embankment

• Minor risk of instability near pond edges if development proposed adjacent

Targeted Investigation Focus

• Soil characterization adjacent to pond embankment

• Hydrogeological study of local groundwater regime

• Assessment of potential pond embankment settlement or instability

Recommended Follow-Up

- Conduct targeted site inspection focusing on pond embankment and soil conditions
- Review local groundwater and drainage reports for pond and creek interaction
- Obtain geotechnical borehole drilling near pond edges to assess soil strength and moisture
- Investigate potential ground stability if proposed construction is near pond margins

Supporting Imagery

current_wide_context — current

Source: mapbox_bbox_wide_context

current_context — current

Source: mapbox_bbox_context

current_site — current

Source: mapbox_bbox_site

historical_qld_1 — 1994 (1994-05-21)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1994_250cm_9543 | Resolution: 250 2

historical_qld_3 — 2013 (2013-09-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2013_10cm_SISP_LGA | Resolution: 10 2

historical_qld_5 — 2022 (2022-07-24)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_LGA_2022_10cm_SISP | Resolution: 10 2

Limitations & Disclaimer

- No subsurface data available; only surface features visible
- Site boundary is approximate based on center area without formal polygon
- Seasonal water variation could affect pond water visibility
- Vegetation cover may obscure small-scale site changes

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.