AI SITE HISTORY REPORT

502 Church Road, Taigum QLD 4018

Generated 07 Apr 2026 | Lat -27.333158, Lng 153.048732 | Confidence: High

Executive Summary

The site at 502 Church Road, Taigum QLD 4018 contains a single on-site former pond feature with vegetation and water presence that has persisted since at least 1995, with surrounding cleared land and some minor earth disturbance near farm structures. Adjacent off-site includes other farm ponds and wooded creek areas. Additional remainder-lot rescan indicates at least one further possible on-site basin/depression should be reviewed.

On-site: One distinct on-site pond feature (Pond A) is centrally located, showing persistent standing water with surrounding vegetation forming a berm-like shape. Minimal disturbance or fill is observed within the lot boundary aside from cleared fields and small farm structures near the southern edge. Remainder-lot rescan also identified additional possible on-site basin/depression features requiring field confirmation.

Adjacent / context: Directly adjacent east outside the site boundary runs a creek with riparian vegetation (Cabbage Tree Creek) and other farm ponds are visible off-site nearby to the south and southwest. Off-site surroundings include cleared agricultural fields and vegetation patches.

Site Details

Address	502 Church Road, Taigum QLD 4018
Location source	polygon
Latitude / Longitude	-27.333158, 153.048732
Site bbox	122.8 m × 101.7 m
Context bbox	176.8 m × 155.7 m
Polygon supplied	Yes

Key Flags

Key Flag	Level	Comment
Former water features	High	Pond A consistently visible with water over decades
Vegetation / land change	Moderate	Clearing evident especially near farm buildings and open paddocks on site
Fill / disturbance	Moderate	Minor earth disturbance near southern structures, no clear evidence of substantial pond fill

Flag Summary

Potential Fill / Disturbance	Moderate
Minor earth disturbance near southern structures, no clear evidence of substantial pond fill	
Former Water Features	High
Pond A consistently visible with water over decades	
Vegetation / Land Change	Moderate

Clearing evident especially near farm buildings and open paddocks on site

Screening Outcome

The site contains one persistent pond on-site with water and vegetated berm from 1995 to present, indicating potential localized moisture and soft soils. Minor earth disturbance exists; no evidence of multiple ponds or extensive fill on-site.

Distinct Feature Review

Feature	Type	Relation	Status	Notes
Pond A	pond	on_site	persistent	Circular former pond with water and vegetation, stable from 1995 through present
secondary_depression_1	depression	on_site	persistent	Small isolated vegetated depression northwest of the main pond; likely seasonal or former minor wetland feature with no standing water currently visible.

Feature Timeline

Pond A — 1995: Filled with water, vegetated perimeter; appears maintained

Pond A — 2005: No significant change; water retained

Pond A — 2011: Continued persistence of pond and vegetation berm

Pond A — current: Water present with berm vegetation; surrounding cleared land, minor farm disturbance near structures

secondary_depression_1 — Unknown period:

Detailed Findings

Visible Observations

• One main circular pond feature visible inside lot on current and historical images

• Vegetation clusters form a berm around pond perimeter

• Standing water within pond area persistent across 1995, 2005, 2011, and current images

• Surrounding land mostly cleared or used as pasture with some scattered trees

• Farm buildings and stored materials present near southern edge of lot

• No distinct second pond on-site identified

• Adjacent creek and additional ponds visible outside site boundary east and south

Overall Change Timeline

1995-2011: Pond A persists with standing water and vegetation; size and shape remain largely unchanged

2011-current: Pond A remains stable with continued water presence and vegetation berm; land use around pond mostly cleared farmland with minor disturbance near buildings

Possible Geotechnical Implications

• Presence of a stable pond feature with water retention potential may indicate zones of higher moisture

• Adjacent creek and pond hydrology could influence site groundwater conditions

• Vegetated berm suggests potential soft or unconsolidated soils around pond perimeter

• Nearby minor fill or disturbance might require localized assessment for stability and compaction

Targeted Investigation Focus

• Soil sampling and in-situ testing around pond berm and basin

- Groundwater monitoring wells near pond and site boundary
- Detailed topographic and geophysical survey of pond area
- Compaction and fill testing near southern farm structure disturbance

Recommended Follow-Up

- Conduct on-site geotechnical investigation focused on pond perimeter and floor for soil moisture and strength
- Assess groundwater and drainage conditions influenced by adjacent creek
- Evaluate extent and impact of minor fill/disturbance near farm structures
- Review historic land use records for any pond maintenance or modifications

Supporting Imagery

current_wide_context — current

Source: mapbox_bbox_wide_context

current_context — current

Source: mapbox_bbox_context

current_site — current

Source: mapbox_bbox_site

current_subzone_west — current

Source: mapbox_bbox_subzone

current_subzone_east — current

Source: mapbox_bbox_subzone

historical_qld_followup_1 — 1995 (1995-06-18)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_1995_60cm_9543 | Resolution: 60 2

historical_qld_followup_4 — 2015 (2015-05-30)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_2015_10cm_SISP_LGA | Resolution: 10 2

historical_qld_followup_6 — 2021 (2021-07-17)

Source: qld_public_imagery | Queensland Digital Orthophoto Image Data - Brisbane_Urban_2021_10cm_SISP | Resolution: 10 2

Limitations & Disclaimer

- No subsurface information available from imagery alone
- Water presence assessment based on visible surface water and vegetation indication
- Temporal resolution limited to selected historic images, potential intervening changes not captured
- Small scale fill or disturbance within site may not be clearly distinguishable

This AI site history scan is a preliminary screening tool only. It is intended to identify possible visual indicators for further professional review. It must not be relied on as a substitute for geotechnical investigation, engineering assessment, or design advice.