
Spindle power without cutting
Program I passes
Program II passes
Quadratic fit on Program I
P_0 without cutting (W)
Spindle speed N (rpm)
300
400
500
600
700
800
1000
1200
1400
1600
1800
2000


Program II: drift at constant speed
Fit of Program I at 1200 rpm (406 W)
P_0 (W)
Pass number (N = 1200 rpm)
410
420
430
440
450
460
470
2
4
6
8
10
12