
Spectrum of the spindle power, Program II pass 3
N/60 = 20 Hz
Air cutting
Cutting
Amplitude (W)
Frequency (Hz)
300
250
200
150
100
50
0
0
10
20
30
40
50