

Program II (N = 1200 rpm): recorded spindle power (shaded: tool in the bar)
Air cutting (no chip)
Cutting
Spindle power (W)
10000
8000
6000
4000
2000
0
0
20
40
60
80
100
120
Time (s)