Essential Home Inspection Services
1103 Hemingway Dr
Greensburg PA 15601
Ph: 724-217-8723

Invoice

REPORT NO:	**15816**
INSPECTION DATE:	**Sept 10, 2026**

CLIENT:

Michael P Milchovich

PROPERTY INSPECTED:

404 9th St
Monongahela PA 15063

Description	Amount
Standard Home Inspection	**$385.00**
Pest Inspection	$100.00
TOTAL	**$485.00**

Thank you for your business

9-10-26
PAID
in full
Ck# 135

Payment of this invoice is due upon receipt. The late payment charge rate of interest is 1.5% monthly (18.0% per annum), after 30 days

Thank You!

Wood Destroying Insect Inspection Report

Notice: Please read important consumer information on **page 2.**

Section I. General Information

Inspection Company, Address & Phone

Essential Home Inspection Services
1103 Hemingway Dr.

Company's Business Lic. No.: BU13571

Date of Inspection: 09/10/2026

Address of Property Inspected:
404 9th St.
Monongahela, PA 1506

Inspector's Name, Signature & Certification, Registration, or Lic. #:
Andrew Joseph
Certification # 409028

Structure(s) Inspected: Home

Section II. Inspection Findings

This report is indicative of the condition of the above identified structure(s) on the date of inspection and is not to be construed as a guarantee or warranty against latent, concealed, or future infestations or defects. **Based on a careful visual inspection of the readily accessible areas of the structure(s) inspected:**

- ☑ **A. No visible** evidence of wood destroying insects was observed.
- ☐ **B. Visible** evidence of wood destroying insects was observed as follows:
  - ☐ 1. Live insects (description and location): _____
  - ☐ 2. Dead insects, insect parts, frass, shelter tubes, exit holes, or staining (description and location): _____
  - ☐ 3. **Visible** damage from wood destroying insects was noted as follows (description and location): _____

NOTE: This is not a structural damage report. **If box B above is checked, it should be understood that some degree of damage, including hidden damage, may be present.** If any questions arise regarding damage indicated by this report, it is recommended that the buyer or any interested parties contact a qualified structural professional to determine the extent of damage and the need for repairs.

Yes ☐ No ☑ It appears that the structure(s) or a portion thereof may have been previously treated. Visible evidence of possible previous treatment: _____

The inspecting company can give no assurances with regard to work done by other companies. The company that performed the treatment should be contacted for information on treatment and any warranty or service agreement which may be in place.

Section III. Recommendations

- ☑ No treatment recommended: (Explain if Box B in Section II is checked) _____
- ☐ Recommend treatment for the control of: _____

Section IV. Obstructions and Inaccessible Areas

The following areas of the structure(s) inspected were obstructed or inaccessible:

- ☑ Basement 6, 9, 11, 13, 24
- ☐ Crawlspace
- ☑ Main Level 1, 3, 4, 6, 7, 8, 9, 11, 13, 24
- ☑ Attic 5, 11, 13, 24
- ☑ Garage 6, 7, 11, 13, 24
- ☑ Exterior 11, 13, 24
- ☑ Porch 11, 13, 24
- ☐ Addition
- ☐ Other

The inspector may write out obstructions or use the following optional key:

1. Fixed ceiling	13. Only visual access
2. Suspended ceiling	14. Cluttered condition
3. Fixed wall covering	15. Standing water
4. Floor covering	16. Dense vegetation
5. Insulation	17. Exterior siding
6. Cabinets or shelving	18. Window well covers
7. Stored items	19. Wood pile
8. Furnishings	20. Snow
9. Appliances	21. Unsafe conditions
10. No access or entry	22. Rigid foam board
11. Limited access	23. Synthetic stucco
12. No access beneath	24. Duct work, plumbing, and/or wiring

Section V. Additional Comments and Attachments

(these are an integral part of the report) _____

Attachments _____

Signature of Seller(s) or Owner(s) if refinancing. Seller acknowledges that all information regarding W.D.I. infestation, damage, repair, and treatment history has been disclosed to the buyer.

X

Signature of Buyer. The undersigned hereby acknowledges receipt of a copy of both page 1 and page 2 of this report and understands the information reported.

X

 © 2004 National Pest Management Association. All Rights Reserved. No reproduction of this form is permitted without the express permission of NPMA
Form NPCA-1 is obsolete after 12/31/04.

Important Consumer Information Regarding the Scope and Limitations of the Inspection

Please read this entire page as it is part of this report. Please refer to the NPMA Suggested Guidelines for instructions on completing this report. This report is not a guarantee or warranty as to the absence of wood destroying insects nor is it a structural integrity report. The inspector's training and experience do not qualify the inspector in damage evaluation or any other building construction technology and/or repair.

1. **About the Inspection:** A visual inspection was conducted in the readily accessible areas of the structure(s) indicated (see Page 1) including attics and crawlspaces which permitted entry during the inspection. The inspection included probing and/or sounding of unobstructed and accessible areas to determine the presence or absence of visual evidence of wood destroying insects. The WDI inspection firm is not responsible to repair any damage or treat any infestation at the structure(s) inspected, except as may be provided by separate contract. Also, wood destroying insect infestation and/or damage may exist in concealed or inaccessible areas. The inspection firm cannot guarantee that any wood destroying insect infestation and/or damage disclosed by this inspection represents all of the wood destroying insect infestation and/or damage which may exist as of the date of the inspection. ***For purposes of this inspection, wood destroying insects include: termites, carpenter ants, carpenter bees, and reinfesting wood boring beetles. This inspection does not include mold, mildew or noninsect wood destroying organisms.*** **This report shall be considered invalid for purposes of securing a mortgage and/or settlement of property transfer if not used within ninety (90) days from the date of inspection. This shall not be construed as a 90-day warranty. There is no warranty, express or implied, related to this report unless disclosed as required by state regulations or a written warranty or service agreement is attached.**

2. **Treatment Recommendation Guidelines Regarding Subterranean Termites:** Treatment or corrective action should be recommended if live termites are found. If no evidence of a previous treatment is documented and evidence of infestation is found, even if no live termites are observed, treatment or corrective action by a licensed pest control company should be recommended. Treatment or corrective action may be recommended if evidence of infestation is observed, and a documented treatment occurred previously, unless the structure is under warranty or covered by a service agreement with a licensed pest control company.
For other Wood Destroying Insects, please refer to the NPMA suggested guidelines for added guidance on actions and or treatment.

3. **Obstructions and Inaccessible Areas:** No inspection was made in areas which required the breaking apart or into, dismantling, removal of any object, including but not limited to: moldings, floor coverings, wall coverings, siding, fixed ceilings, insulation, furniture, appliances, and/or personal possessions; nor were areas inspected which were obstructed or inaccessible for physical access on the date of inspection. Your inspector may write out inaccessible areas or use the key in Section IV. Crawl spaces, attics, and/or other areas may be deemed inaccessible if the opening to the area is not large enough to provide physical access for the inspector or if a ladder was required for access. Crawl spaces (or portions thereof) may also be deemed inaccessible if there is less than 24 inches of clearance from the bottom of the floor joists to the surface below. If any area which has been reported as inaccessible is made accessible, the inspection company may be contacted for another inspection. An additional fee may apply.

4. **Consumer Maintenance Advisory Regarding Integrated Pest Management for Prevention of Wood Destroying Insects.** Any structure can be attacked by wood destroying insects. Homeowners should be aware of and try to eliminate conditions which promote insect infestation in and around their structure(s). Factors which may lead to wood destroying insect infestation include: earth to wood contact, foam insulation at foundation in contact with soil, faulty grade, improper drainage, firewood against structure(s), insufficient ventilation, moisture, wood debris in crawlspace, wood mulch or ground cover in contact with the structure, tree branches touching structure(s), landscape timbers and wood decay. Should these or other conditions exist, corrective measures should be taken in order to reduce the chances of infestation of wood destroying insects and the need for treatment.

5. **Neither the inspecting company nor the inspector has had, presently has, or contemplates having any interest in the property inspected.**

 © 2019 National Pest Management Association. All Rights Reserved. No reproduction of this form is permitted without the express permission of NPMA

Previous editions are obsolete after 12/31/19. This form is approved for FHA and VA loans.