

Master CNC Codes Reference Guide

Comprehensive Table of G-Codes, M-Codes, and Machine Parameters

G - Codes (Preparatory Functions)			M - Codes (Miscellaneous Functions)			Other Machine Codes		
#	Code	Function	#	Code	Function	#	Code	Function
1	G00	Rapid Linear Movement	1	M00	Program stop	1	X	X- Axis (Linear)
2	G01	Feed Linear Movement	2	M01	Optional stop	2	Y	Y - Axis (Linear)
3	G02	Clock Wise Movement	3	M02	End of program	3	Z	Z - Axis (Linear)
4	G03	Counter Clockwise Movement	4	M03	Spindle on Clockwise	4	C	C - Axis (Degree)
5	G04	Dwell / Stopping Intervals	5	M04	Spindle on Counter-clockwise	5	I	I- Axis
6	G05		6	M05	Spindle Stop	6	J	J- Axis
7	G06		7	M06	Tool Change	7	K	K- Axis
8	G07	Imaginary Axis Designation	8	M07		8	Q	Distance for Step Movement
9	G08		9	M08	Coolant On	9	D	Daimeter
10	G09		10	M09	Coolant off	10	S	Speed
11	G10	Data Setting	11	M10	Clamp	11	F	Feed
12	G11	Data setting mode cancel	12	M11	Unclamp	12	P	Dwell Time
13	G12		13	M12		13	O	Program Naming
14	G13		14	M13		14	N	Program Line
15	G14		15	M14		15	T	Tool Number
16	G15		16	M15		16	H	Offset Number

G - Codes (Preparatory Functions)		
#	Code	Function
92	G91	Incremental measurements
93	G92	
94	G93	
95	G94	Feed per minute
96	G95	Feed per revolution of the spindle
97	G96	Constant surface speed control
98	G97	Constant surface speed control Cancel
99	G98	Return to initial point in canned cycle
100	G99	Return to R point in canned cycle

M - Codes (Miscellaneous Functions)		
#	Code	Function
92	M91	
93	M92	
94	M93	
95	M94	
96	M95	
97	M96	
98	M97	
99	M98	Call SubProgram
100	M99	End Subprogram

Other Machine Codes		
#	Code	Function