

Timed turns
Linear fit (used)
Quadratic fit (check)
Settings of the photos
ω (rad s⁻¹)
2.0
1.5
1.0
0.5
0.0
(a)
(ω − fit)/ω (%)
2
0
−2
(b)
Linear
Quadratic
0
20
40
60
80
Motor setting S