Date	Description of Work	Hours
29-Feb	Complete layout of IMU External	1.5
1-Mar	Generate Artwork, BOM, Drill Files for IMU External	0.5
	Fix exposed copper issue on 0402 components, generate new	
4-Mar	Schematic/PCB PDFs	0.25
7-Mar	Fix issue on IMU External where trace is too close to the edge	0.25
	Create troublshooting guide to identify issues with first assmebly of	
15-Mar	prototype	1
	Update IMU footprint for Sleeptrack and IMU External board. (Pitch Change from .53mm to.43mm spacing.) Other small changes(tented	
20-Mar	vias, USB footprint, move Vias, clean up stray/long traces)	1
	Total:	4.5