



8, lagos street

Property Damage Analysis

Professional Assessment Report

PROPERTY ADDRESS

123 example street

INSPECTION DATE

18 September 2025

PREPARED FOR

john smith
ljhg;ikhv;hkvk

PREPARED BY

Julius Ayolyn

Executive Summary

This comprehensive report presents the findings of an AI-assisted property damage analysis conducted for the above-mentioned property. Our advanced analysis system has identified **3** areas of concern that require professional attention and remediation. The assessment includes detailed damage documentation, prioritized recommendations, and preliminary cost estimates to guide your decision-making process.



Video Analysis Performed

Comprehensive video analysis was conducted for this property inspection.

Note: Video files cannot be embedded in PDF reports for technical reasons.



Damage Assessment

1 **HIGH** Exposed Underlayment: Large sections of the roof deck are exposed due to missing or damaged shingles. This leaves the underlayment vulnerable to weather damage and poses a significant risk of leaks. Severity: High. Recommendation: Replace all missing or damaged shingles and repair any damaged underlayment. Ensure proper sealing around all penetrations and flashings. Location: Not specified.

2 **MEDIUM** Flashing Damage: The flashing around the roof penetration appears damaged or improperly installed. This can lead to water infiltration and subsequent damage to the roof structure. Severity: Medium. Recommendation: Inspect and repair or replace the flashing around the roof penetration. Ensure proper sealing to prevent water ingress. Location: Not specified.

3 **MEDIUM** Missing Shingle: Several shingles appear to be missing or damaged, particularly near the exposed underlayment. This exacerbates the risk of water intrusion. Severity: Medium. Recommendation: Replace missing shingles and assess surrounding shingles for damage. Replace or repair as needed. Location: Not specified.



Professional Recommendations

Schedule a professional roof inspection for a thorough assessment and repair estimate.

Prioritize repairs for the exposed underlayment and flashing damage to prevent further deterioration.



Cost Analysis

Exposed Underlayment: £1500–£3000

Flashing Damage: £500–£1000

Missing Shingle: £500–£1000

Important Legal Disclaimer

This analysis is AI-assisted and must be verified by a certified professional inspector. Estimates are approximate and may vary depending on contractor rates and material availability.

Report generated on 1 October 2025

Document ID: 9AD4BD77