		tc	39	81 19	64 23	و ي	21 29	5 2	വവ	25 37	87 39	26	21 45	95 48	<u></u>
DING SPINDLE	Upper Figures Denote Threading Spindle Speed Lower Figures Denote Effective Threading Spindle Speed	High Side-Threading Clutch Threading Change Gears	25-39	481 19	564 23	656 26	721	809 32	865 35	925 37	987 39	1082 43	112 4	119	1273
			24-40	450 50	528 59	614 68	675 75	757 84	810 90	96 96	923 103	1013 112	1049	1119 124	1192 132
			23-41	421 79	86 11611	574 108	631 119	708 133	757 143	809 153	863 163	947 178	981 185	1046 197	1114 210
			21-42	375 125	ረቱ1 0ቱቱ	512 170	563 187	631 210	675 225	722 240	770 256	844 281	874 292	932 311	993 331
		Using T	20-44	341 159	400 187	465 217	511 239	573 268	614 286	656 306	700 326	767 358	795 371	848 395	903 421
		Using Low Side Of Threading Clutch Threading Change Gears	36-28	482. 18	566 21	658 24	723 27	811 30	868 32	928 34	989 37	1085 40	1124 42	1199 44	1277 47
			35-29	453 47	531 56	617 65	679 71	761 80	815 85	871 91	929 97	1018	1055	1125	1198 126
			34-30	425 75	88 88	580 102	638 112	714 127	765 135	818 144	872 154	956 169	991 175	1057 186	1125 199
			33-31	399 101	469 118	544 138	599 151	671 170	719	768 194,	819 ° 207	898 227	931 235	992 251	1057 267
			32-32	375 125	440 147	511 171	563 187	631 210	675 225	721 241	770 256	844 281	874 292	932	993 331
			31-33	352 148	414 173	480 202	528 222	593 248	634 266	678 284	723	793 332	821 345	876 367	933 391
			30-34	331 169	388 199	451 231	496 254	557 284	596 304	637	679	744 381	772 394	823 420	876 448
			29-35	311	365 222	424 258	466 284	523 318	559 341	598 364	638 388	699	725 441	772	823 501
		:	28-36	292 208	342 245	398 284	438 312	491 350	525 375	561 401	599 427	656 469	984	725 518	772 552
		Spindle Change Gears		16-48	18-46	20-44	21-42	23-41	24-40	25–39	26-38	27-36	28-36	29-35	30-34
		Spindle Speed C		200	587	682	750	841	006	962	1026	1125	. 1166	1243	1324

14° m

Page 128