6:1 THREADING TABLE																
		12	14	16	18	20	22	24	26	28	30	32	34	36	38	40
		11	10	10	10	10	9	9	9	9	9	9	8	8	8	8
768	128	•9	1.2	1.06	.94	.85	1.2	1.13	1.05	.97	.9	.85	1.2	1.15	1.09	1.04
		11	10	10	10	10	10	9	9	9	9	9	8	8	8	8
774	129	.91	1.2	1.07	•95	.86	.78	1.14	1.05	.98	.91	.85	1.2	1.16	1.1	1.05
		11	10	10	10	10	10	9	9	9	9	9	9	8	8	8
780	130	-92	1.2	1.08	.96	•86	.79	1.15	1.06	.99	•92	.86	.81	1.16	1.1	1.05

RISE AND DROP OF 6:1 THREADING CAMS ARE AS FOLLOWS:							
CAM NO.	RISE	HUNDREDTHS	DROP	HUNDREDTHS			
1	.118"	0 to 32½	.137"	32 _호 to 50			
2	.200"	0 to 32½	.232"	32½ to 50			
3	.317*	0 to 32½	.366"	32½ to 50			
4	.452"	0 to 32½	.540"	32½ to 50			
5	.715"	0 to 32½	.825"	32½ to 50			
6	1.140"	0 to 32½	1.320"	32½ to 50			
7	1.740"	0 to 32½	2.100"	$32\frac{1}{2}$ to 50			
8	2.000"	$8\frac{1}{2}$ to $32\frac{1}{2}$	2.000"	$32\frac{1}{2}$ to $43\frac{1}{4}$			
9	2.000"	$16\frac{1}{2}$ to $32\frac{1}{2}$	2.000"	$32\frac{1}{2}$ to $39\frac{1}{2}$			
10	2.000"	22½ to 32½	2.000"	32½ to 37			
11	2.000"	27 to $32\frac{1}{2}$	2.000"	$32\frac{1}{2}$ to $35\frac{1}{4}$			