

NOTE: MB-43 PULLEY IS LOCATED APPROXIMATELY 1/4" FROM MB-2.

NOTE: TAPER SLEEVE IN BEARING MUST BE TEMPORARILY KEYED TO MB-9 SHAFT WHEN TIGHTENING LOCK NUT. REMOVE KEY AFTER ASSEMBLY.