| TABLE OF CONTENTS | PAGE |
|--|--|
| TO CUT RIGHT OR LEFT HAND THREADS | 81 |
| USING THE REVERSING BLOCK | 84 |
| SUPPORTING WITH THE THREADING SPINDLE | 84 |
| DRILLING WITH THE THREADING SPINDLE | 85 |
| CAPACITY - REGULAR & OVERSIZE MACHINE | 86 |
| GENERAL INFORMATION | 87 |
| CAMS | 90 |
| GEARS | 93 |
| DECIMAL CONVERSION CHART | 94 |
| FORM TOOL CHARTS | 96 |
| SIZING TOOL CHARTS | 102 |
| PRINCIPAL DIMENSIONS | 115 |
| CYCLE TIME AND FEED GEAR TABLE: 75 Cycle | 116 |
| 60 Cycle 45 Cycle | 120 124 |
| SPINDLE GEARS AND SURFACE FEET (Per Minute): 75 Cycle 60 Cycle 45 Cycle | 118 |
| SPINDLE GEARS AND SURFACE METERS (Per Minute): 75 Cycle 60 Cycle 45 Cycle | 119 123 127 |
| THREADING SPINDLE SPEEDS FOR SELF-OPENING DIE HEADS: 75 Cycle 60 Cycle 45 Cycle | 128 130 132 |
| 6:1 THREADING METHOD TABLE: 75,60,45 Cycle in Inches 75,60,45 Cycle in Millimeters | 135 142 |
| 2:1 THREADING METHOD TABLE: 75 Cycle in Inches 75 Cycle in Millimeters 60 Cycle in Inches 60 Cycle in Millimeters 45 Cycle in Inches 45 Cycle in Millimeters | 146 149 147 150 148 151 |
| TROUBLE SHOOTING | 153 |
| PREVENTIVE MAINTENANCE | 155 |