

Risk Assessment No: WP-002				Task: Feed Hopper & Apron Feeder — feeding and blockage clearance							
Prepared By: Derick Bibby				Date: 02.08.2026			RA Review Date: 01.08.2027				
				Reviewed By: Lee Hardy			Date: 02.08.2026				
PPE: Safety Footwear, High Visibility Jacket, High Visibility Trousers, Hard Hat, Gloves, Ear Defenders, Mask, Eye Protection											
Hazard	Persons at Risk	L	S	R	Control Measures				L	S	R
Fall into feed hopper from tipping edge or grid	Loader driver (dismounted) Maintenance	3	5	15	- Loader driver remains in cab during tipping — no dismount at hopper edge. - Grid intact and locked; opened only under permit for cleaning. - Full LOTO of apron feeder before any grid opening. - Fall-arrest anchor point and harness for any planned work over the hopper. - Wheel-stops and edge protection maintained.				1	5	5
Entanglement / crushing in apron feeder chain and skirts	Maintenance Cleaners	3	5	15	- Full LOTO of apron feeder hydraulic and electrical supplies before entry. - Chain movement not permitted with any person within the feeder body. - Skirt-rubber changes carried out with feeder locked off and blocked against gravity movement.				1	5	5
Blockage clearance from feed hopper or chute	Operator Loader driver	4	4	16	- Never clear a blockage from above the grid with hands or a bar while the feeder is live. - Isolate feeder, verify zero energy, then clear blockage using long-handled tool or telehandler with attachment. - For blockages requiring entry, apply Confined Space RA WP-011.				1	4	4
Struck by mobile plant (wheel loader, telehandler, tipper wagons)	Operator Loader driver Wagon drivers Visitors	4	5	20	- Traffic Management Plan segregates pedestrians from mobile plant. - Wheel loader fitted with reversing alarm, camera and beacons. - Wheel-stops at feed hopper; banksman when reversing at hopper. - Radio protocol between wash-plant operator and loader driver. - Visitors escorted at all times; hi-vis and site induction mandatory.				1	5	5
Exposure to respirable crystalline silica (RCS) and other dusts	Operator Picking staff Loader driver	4	4	16	- Plant runs wet — spray bars on scalping and sizing screens for suppression. - Water suppression at feed hopper and stockpile transfer points. - FFP3 mask when dry-handling filter cake or working downwind of dust sources. - Air-conditioned cabs with positive-pressure filtered air on all mobile plant. - Personal RCS monitoring on rolling programme under health surveillance. - No dry-sweeping — vacuum or damp-down only.				2	4	8
Slips, trips and falls on	All plant	4	3	12	Anti-slip walkways and stair-treads; wash-down at end of shift.				2	3	6

the same level	personnel				● No trailing hoses or cables across walkways — stored on reels or coiled. ● Immediate clean-up of oil, hydraulic fluid or fines spillage. ● Adequate task lighting throughout the plant. ● Correct footwear with slip-resistant sole to SRC.			
Stored energy — hydraulic accumulators, pneumatic receivers	Maintenance Contractors	3	5	15	● Bleed hydraulic accumulators to zero pressure and confirm via gauge before opening manifolds. ● Drain air receivers to zero via test valve before hose or fitting removal. ● Padlock the isolator on the pump or compressor supplying the circuit. ● PSSR examination of accumulators and receivers at statutory interval.	1	5	5