

A001-DIR-2026-09 / APPROVED

A-001 Detailed Inspection Report - September 2026

A-001 | Cooling Water Pump | Enterprise Asset Reliability Training Scenario

Document ID	A001-DIR-2026-09	Version	1.0
Status	APPROVED	Effective / Issue Date	2026-09-05
Owner	Mechanical Inspection Team	Asset	A-001
Location	Utilities Area - Bay 3	Data Class	Synthetic / Training

TRAINING NOTICE: This fictional document is designed only for AI/RAG, analytics and governance training. It is not an engineering instruction and must not be used on real equipment.

1. Inspection Objective

This training inspection was initiated after the August condition-monitoring report identified a sustained vibration increase and the inspection work order WO-2026-0817 remained open. The objective was to record observable condition evidence and identify information requiring qualified reliability review.

2. Inspection Scope

Area Reviewed	Training Observation	Evidence Status
External condition	No visible leakage recorded during the training walkthrough	Observed
Coupling / alignment area	Minor witness-mark offset noted; no root cause assigned	Observed
Bearing housing	Surface temperature reading remained within the recent training range	Observed
Vibration indication	Elevated relative to the earlier-month baseline	Corroborated
Work history	WO-2026-0817 still open at time of review	Structured record

3. Measurement Snapshot

Timestamp	Vibration RMS (mm/s)	Bearing Temp (C)	Comment
2026-09-03 09:00	6.2	70	Training inspection sample
2026-09-03 09:30	6.3	71	Repeat reading
2026-09-03 10:00	6.1	70	Stable within inspection window

4. Inspection Findings

- The vibration indication remains above the earlier August baseline used in A001-CMR-2026-08.
- The limited inspection evidence does not establish a confirmed failure mechanism.
- The coupling witness-mark observation is relevant context but requires qualified interpretation.
- Open maintenance work should be reviewed before any condition conclusion is finalized.

5. Risk Interpretation

The combined inspection evidence supports continued review under the enterprise reliability policy. This report does not authorize repair, shutdown or maintenance scope. Any action must be based on the current approved procedure and qualified human review.

6. Evidence Traceability

Claim	Supporting Source
Vibration remains elevated relative to earlier baseline	Inspection measurements / A001-CMR-2026-08
An inspection work order remains open	WO-2026-0817
Current inspection guidance is version 2.0	A001-PROC-INS-001-V2
No confirmed failure mode is established	This report / condition-monitoring report

7. Open Questions

- Do the full-resolution sensor readings show the same pattern as the sampled inspection values?
- Has any maintenance activity occurred since the August field condition report?
- Does the coupling observation persist after the next approved inspection cycle?

8. Reviewer Sign-off

Role	Status
Mechanical Inspector	Report issued
Reliability Reviewer	Pending review
Maintenance Planner	Pending work-order review