date: 2003/06/05

RENESAS TECHNICAL UPDATE

Classification of Production	Development Environment			No	TN-EML-110A/E	Rev	1.0
ТНЕМЕ	Notes on Usage of the USB Adapter for E6000/E8000 Emulator (HS6000EIU01) Classification of Information		 Spec change Supplement of Documents Limitation of Use Change of Mask Change of Production Line 				
PRODUCT NAME	HS6000EIU01	Lot No.		USD Adoptor for E6000/E9000		Term of Validity	
		All lots	Reference Documents	USB Adapter for E6000/E8000 Emulator HS6000EIU01H Description Notes ADE-702-325(Rev.1.0)		Permar	Permanent

1. Overview

We have modified the USB driver (new file version: 6.0.01.000) because there is a problem that the emulator does not start up correctly when the USB Adapter for E6000/E8000 Emulator (HS6000EIU01; hereafter referred to as the USB adapter) is in use to connect the E8000, E8000S, E6000, or E6000H emulator to certain host computers, in which Windows® 98SE* has been installed. This problem can be solved by updating the USB driver on the host computer.

Note: Windows® 98SE is an abbreviation for Microsoft® Windows® 98 Second Edition operating system.

2. Conditions

This problem is relevant to certain host computers in which Windows® 98SE has been installed. . Updating of the USB driver is only necessary in cases where the emulator does not start up correctly even though Windows® 98SE recognizes the USB driver.

3. Solution

Download the USB driver, which is provided as a solution to this problem, and the document 'Updating the USB Driver for the E6000/E8000 Emulator' from one of the following websites to update the USB driver used with a host computer this problem is relevant to.

E6000 emulator:

http://www.renesas.com/eng/products/mpumcu/tool/download/emulator/e6000/driver.html

E6000H emulator:

http://www.renesas.com/eng/products/mpumcu/tool/download/emulator/e6000h/index.html

E8000/E8000S emulator:

http://www.renesas.com/eng/products/mpumcu/tool/download/emulator/e8000/driver.html