MWM Acteon Engine Troubleshooting Manual PDF Index

S12018a Contents

PCode P0087 Low pressure on fuel line

thru

PCode P0123 High voltage on accelerator position sensor

S12018b Contents

PCode P0190 Fuel pressure above system maximum limit

thru

PCode P0264 Short circuit to ground on injector #2

S12018c Contents

PCode P0265 Short circuit to battery voltage on injector #2

thru

PCode P0522 Low voltage on lubricating oil pressure sensor

S12018d Contents

PCode P0523 High voltage on lubricating oil pressure sensor

thru

PCode P1008 High voltage on internal capacitor Bank 2

S12018e Contents

PCode P1087 Pressure leakage while turning off engine

tnru

PCode P1206 Failure on monitoring signal from injector #6

S12018f Contents

PCode P1237 Voltage supply low on intake air pressure sensor

thru

PCode P2269 Presence of water on fuel