Authorized Field Change

AFC G-07908

Date: July, 2007

Subject File: Front End Sheet Metal

Subject: Warning Labels

Model: 7300, 7400, 7500

DESCRIPTION

International Truck and Engine Corporation has determined that the ether warning label may be missing or not visible on the air intake and air cleaner housing.

PARTS INFORMATION

Table 1 Parts: LABELS WERE SHIPPED DIRECTLY TO CUSTOMERS.

Part Number	Description	Quantity
3566200C3	Ether Warning Label	1

SERVICE PROCEDURE

WARNING – To avoid personal injury or death, shift transmission to park or neutral, set parking brake, and block wheels before doing diagnostic or service procedures.



Figure 1

SERVICE PROCEDURE (CONT.)

- 1. Clean hood, (DRIVERS SIDE) below black intake grille area, of grease and dirt prior to applying the label (Figure 1).
- 2. Affix label to hood as per Figure 2.



Figure 2

Operation number must appear on all claims.

Table 2 Labor Information


Operation No.	Description	Time
A40-07908-1	Install label	0.4 Hr.

ADMINISTRATIVE PROCEDURE

Expense is to be charged to Warranty. Claims are to be submitted in the normal manner, making reference to Authorized Field Change Number G-07908

It is important that the coding be completed properly to assist in processing the warranty claim. Complete instructions will be found in the Warranty Manual, Section 7–1. Special attention should be given to Items 39 through 44.

To assure this important improvement is made in a timely manner, all claims for G-07908 activity must be submitted by July 31, 2008 or within the normal warranty period for the vehicle, if after July 31, 2008.



3

Distribution: All except J-81 Reproduction: Not required.