Authorized Field Change



AFC 03904

Date: March, 2003

Subject File: GENERAL

Subject: Removal of Part Number 3566852C1 Certification Label on certain 9400i models built at Escobedo from 8/26/99 through 5/28/01

Model: 9400i

Start Date: 08/26/1999 End Date: 05/28/2001

DESCRIPTION

This campaign covers 9400i models built without anti-lock brakes (ABS) from 8/26/99 through 5/28/01 at the Escobedo Plant.

The vehicles identified above may have certification label 3566852C1 (see Figure 1) mistakenly installed on the inside door opening on the driver side. This label certifies that the vehicle conforms to all applicable U.S. Motor Vehicle Safety Standards. Because these vehicles do not have anti-lock brakes (ABS), the vehicle DOES NOT CONFORM to all U.S. Motor Vehicle Safety Standards.




Figure 1 Navistar NETS Window

DESCRIPTION (CONT.)

ACTION REQUIRED

All 9200 and 9400i models without anti-lock brakes (ABS) should be inspected for 3566852C1 certification label when the vehicle is brought in for service. If label part number 3566852C1 is found installed on a vehicle without anti-lock brakes (ABS), the label must be removed.

Operation number must appear on all claims.

Table 1 Labor Information


Operation No.	Description	Time
A40-03904-1	Remove Certification Label	0.3 Hr.

ADMINISTRATIVE PROCEDURE

Mexican locations are to submit warranty claims in the usual manner making reference to Authorized Field Change Number G-03904.

It is important that the coding be completed properly to assist in processing the warranty claim. Complete instructions will be found in the Warranty Manual, Section 7–1. Special attention should be given to Items 39 through 44.

To assure this important improvement is made in a timely manner, all claims for G-03904 activity must be submitted by April 30, 2004 or within the normal warranty period for the vehicle, if after April 30, 2004.



Distribution: All except J-81 Reproduction: Not required.

AFC-03904 2