Veterinary Suite Condition Register

Visit Details

Claim: CLM-26-876731. Property: Oak Terrace Veterinary Clinic LLC, 1539 Alder Court, Suite D.

Inspection completed 2026-08-25 by Elliot Chen.

The examination corridor and utility alcove were inspected six days after the reported release. Fresh standing water had been removed before attendance. At the base of the utility wall, the visible materials have more than one appearance: bright wet cut edges beside dull brown staining beneath an older paint layer.

Interior Scope

Newly opened gypsum is wet at the examination-room return. Farther down the same utility route, the lower paper separates behind a brown paint blister. Several plank joints are raised over the route, and a ceiling panel shows both a pale outer ring and a darker central stain. The inspection sketch records the visible boundary without assigning dates to individual finish changes.

Microbial Observations

Patchy surface discoloration was visible on the concealed utility backing. No sample was collected and no separate environmental work schedule was presented. The current estimate prices finish replacement, not a separately scoped remediation contract.

Prior Conditions

One opening contains fresh pale splinters next to dark softened timber. There are two paint layers over a blister at the wall foot. The caretaker pointed to the same utility route mentioned in the maintenance ledger; that ledger was not reproduced in this condition register.

Electrical Scope

Low outlets along the utility route have moist cable entries. Two boxes carry dull deposits below fresh droplets; the farthest dry control box has neither. The electrician isolated this branch during the visit. The condition sheet records the observations but contains no earlier test readings for these outlet positions.

Millwork Scope

The utility base panel is swollen around its fixing screws, with a dark ring under the washer at one fixing. Adjacent kickboards have lifted after the reported release. The counter surface remains flat. No dated close-up of the panel backing was supplied during the inspection.

Demolition Scope

The proposed removal strip follows the wet wall bases and raised floor joints through the examination corridor. Behind the utility plinth, the substrate crumbles below an older paint layer. Removal will expose the remaining pipe route; at this visit, the closed section beyond the alcove could not be seen.

Mitigation Necessity

The drying contractor's site record places extraction and air movement along utility alcove and exam-room return. Wet cores and released adhesives were still visible at the survey openings. The crew logged equipment placement, follow-up moisture readings and removal of the drying equipment. Temporary barriers kept the wet work route clear of the retained occupied areas.

Veterinary Suite Condition Register

Trade Coordination

The examination corridor remains the staff access route. Work has to move from the alcove toward the side exit in stages, with electrical isolation maintained during each wall opening. The back of the remaining base panel cannot be inspected until removal starts.

The inspector's trade-sequencing allowance is 10% combined overhead and profit on the building repair trades. Separate vendor services carry their own mobilization and supervision in their prices.

Room Observation Register

Comparative meter readings are unitless indices on a 0-100 scale, not moisture percentages. Each room spot is compared with an adjacent retained substrate on the same instrument setting. Readings describe the visit condition and do not date the wetting.

Point / location	Assembly / record	Observation / method	Boundary / reference
1A - Utility alcove	Backing beneath older paint	dark softened timber beside pale wet cut	Age of concealed change not measured
1B - Utility alcove	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-25; sample point 1
1C - Utility alcove	Lower substrate spot reading	76 on relative 0-100 scale	Accessible surface beside backing beneath older paint
1D - Utility alcove	Retained comparison point	11 on same instrument scale	Age of concealed change not measured
2A - Exam-room return	Fresh gypsum opening	wet bright core	First opened at this visit
2B - Exam-room return	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-25; sample point 2
2C - Exam-room return	Lower substrate spot reading	55 on relative 0-100 scale	Accessible surface beside fresh gypsum opening
2D - Exam-room return	Retained comparison point	13 on same instrument scale	First opened at this visit
3A - Corridor ceiling	Stained infill panel	pale ring outside darker center	No dated panel photograph
3B - Corridor ceiling	Inspection method	Visual survey of exposed surfaces and access opening	Field visit 2026-08-25; sample point 3
3C - Corridor ceiling	Lower substrate spot reading	66 on relative 0-100 scale	Accessible surface beside stained infill panel
3D - Corridor ceiling	Retained comparison point	9 on same instrument scale	No dated panel photograph

Veterinary Suite Condition Register

Schedule continued

Point / location	Assembly / record	Observation / method	Boundary / reference
4A - Plant position	Motor housing lower vents	dull deposits below fresh water mark	Earlier test sheet not supplied
4B - Plant position	Inspection method	Electrical inspection after isolation	Field visit 2026-08-25; sample point 4
4C - Plant position	Lower substrate spot reading	77 on relative 0-100 scale	Accessible surface beside motor housing lower vents
4D - Plant position	Retained comparison point	11 on same instrument scale	Earlier test sheet not supplied

Inspection Record

Working notes were entered during the 2026-08-25 visit. Room labels in the table follow the site route used by Elliot Chen; they are not contractor estimate line numbers.

The table records inspected positions and comparison areas. It is not a full quantity takeoff or an invoice. Closed assemblies are distinguished from opened observations in the narrative.