Utility Plant Condition Sheet

Assessment Record

Operator: Birchstone Dental Lab LLC. Location: 1624 Alder Court, Suite D.

Claim CLM-26-348735; examination date 2026-09-03.

Condition and Repairability

The laboratory compressor and extraction vacuum were housed below the fabrication bench. Water reached their motor vents. The service report records winding insulation failures in both and matching replacement assemblies. The laboratory owns the equipment and retained the existing air and suction connections.

Test Record

Assembly	Observed test condition	Service route
Compressor	Water entry at motor/control assembly	Matching replacement assembly
Vacuum unit	Winding insulation failure after drying	Matching replacement assembly

Pricing Scope

This equipment examination records condition, repair route and asset identity. The subsequent vendor quotation contains the installation and disposal prices.