Connection Repair Work Order

Service Record

Customer: Lakeshore Surgical Center LLC. Claim reference: CLM-26-366148.

Visit: 2026-08-22. Address: 1573 Alder Court, Suite F.

Cause Assessment

A pressurized connector within the corridor service spine separated overnight. The facilities engineer closed the building branch after water appeared at several ceiling joints. The replacement connector held pressure while the spine remained exposed. The water path follows the spine rather than an external wall or roof penetration.

Work Notes

The service ticket was closed on 2026-08-22 after the connection test. The technician recorded work at the connection and the accessible immediate area. Finish reinstatement was not carried out under this ticket.