Scope and Price Comparison

Review Assignment

Cost file for Harborview Diagnostics LLC, CLM-26-902082. Prepared by Cypress Independent Surveyors on 2026-08-30.

The estimate separates the water-damaged finishes from the physical access route. Line L4 prices opening and reinstatement of the dry passage strip and return panel. The other repair lines price the wet room assemblies. The plumber's failed connection itself is not included in these finish allowances.

The comparison uses current local trade prices for the described work. Lump-sum allowances include normal labor, materials, waste and access within each priced scope. Prices are in USD before tax.

Reviewed Line L1

Interior finish repairs

Submitted line: $50,000.00. Independently reviewed lump-sum allowance: $50,000.00.

The comparison includes the removal and reinstatement operations listed for this trade, within the marked work boundary.

Reviewed Line L2

Flooring replacement

Submitted line: $25,000.00. Independently reviewed lump-sum allowance: $25,000.00.

Scope reference: Diagnostic room and the associated removal/reinstatement boundaries in the survey.

Reviewed Line L3

Cabinetry repair

Submitted line: $15,000.00. Independently reviewed lump-sum allowance: $15,000.00.

The allowance follows the independent takeoff and local trade comparison recorded in this cost file.

Reviewed Line L4

Access and tear-out to reach failed plumbing

Submitted line: $30,000.00. Independently reviewed lump-sum allowance: $30,000.00.

The comparison includes the removal and reinstatement operations listed for this trade, within the marked work boundary.

Reviewed invoice_01

Vendor charges on invoice_01: $20,000.00.

The independently accepted price is $20,000.00. The service descriptions and duration were compared with the vendor work record and local service pricing.

Reviewed invoice_02

Vendor charges on invoice_02: $10,000.00.

The independently accepted price is $10,000.00. The service descriptions and duration were compared with the vendor work record and local service pricing.

Scope and Price Comparison

Price Comparison Schedule

Line	Scope description	Submitted	Review opinion
L1	Interior finish repairs	$50,000.00	$50,000.00
L2	Flooring replacement	$25,000.00	$25,000.00
L3	Cabinetry repair	$15,000.00	$15,000.00
L4	Access and tear-out to reach failed plumbing	$30,000.00	$30,000.00