# Connection Repair Work Order

## Service Record

Customer: Harborview Diagnostics LLC. Claim reference: CLM-26-902082.

Visit: 2026-08-16. Address: 1471 Alder Court, Suite E.

## Cause Assessment

A compression nut on the concealed cold-water branch loosened above the passage ceiling. Closing the floor isolation valve stopped the flow. The connection could be seen through a small camera hole but could not be reached with a wrench through that opening. The leak point lies behind two finish layers and a fixed return panel.

## Work Notes

The service ticket was closed on 2026-08-16 after the connection test. The technician recorded work at the connection and the accessible immediate area. Finish reinstatement was not carried out under this ticket.