Motor and Control Test Record

Assessment Record

Operator: Redstone Family Dentistry LLC. Location: 1641 Alder Court, Suite E.

Claim CLM-26-475747; examination date 2026-09-04.

Condition and Repairability

The compressor and vacuum in the low recess have fresh water marks at their electrical entries. The service technician recorded persistent insulation failure after drying. Replacement units use the existing footprint and output ratings. Their serial numbers appear in the practice asset record.

Test Record

Assembly	Observed test condition	Service route
Compressor	Water entry at motor/control assembly	Matching replacement assembly
Vacuum unit	Winding insulation failure after drying	Matching replacement assembly

Pricing Scope

This equipment examination records condition, repair route and asset identity. The subsequent vendor quotation contains the installation and disposal prices.