Motor and Control Test Record

Assessment Record

Operator: Westfield Orthodontics LLC. Location: 1590 Alder Court, Suite B.

Claim CLM-26-678338; examination date 2026-09-01.

Condition and Repairability

The store compressor and vacuum motor housings have water marks across their vents. Tests after drying found failed insulation in the sealed winding assemblies. The equipment engineer matched replacement ratings to the original asset labels. Installation uses the existing connections.

Test Record

Assembly	Observed test condition	Service route
Compressor	Water entry at motor/control assembly	Matching replacement assembly
Vacuum unit	Winding insulation failure after drying	Matching replacement assembly

Pricing Scope

This equipment examination records condition, repair route and asset identity. The subsequent vendor quotation contains the installation and disposal prices.