Equipment Workshop Findings

Assessment Record

Operator: Cypress Point Endoscopy LLC. Location: 1658 Alder Court, Suite F.

Claim CLM-26-591035; examination date 2026-09-05.

Condition and Repairability

The compressor and vacuum in the plant compartment have water entry at their control housings and failed winding insulation tests. The equipment specialist compared replacement units against the original stock numbers and capacity plates. Both are listed on the clinic's owned-asset register.

Test Record

Assembly	Observed test condition	Service route
Compressor	Water entry at motor/control assembly	Matching replacement assembly
Vacuum unit	Winding insulation failure after drying	Matching replacement assembly

Pricing Scope

This equipment examination records condition, repair route and asset identity. The subsequent vendor quotation contains the installation and disposal prices.