Plumbing Attendance Sheet

Service Record

Customer: Cypress Point Endoscopy LLC. Claim reference: CLM-26-591035.

Visit: 2026-08-27. Address: 1658 Alder Court, Suite F.

Cause Assessment

A flexible inlet beneath the instrument-cleaning unit split close to the threaded tail. The plumber closed the inlet, removed the damaged hose and tested the replacement through several fill cycles. The unit's waste connection remained tight during those cycles.

Work Notes

The service ticket was closed on 2026-08-27 after the connection test. The technician recorded work at the connection and the accessible immediate area. Finish reinstatement was not carried out under this ticket.