

MANGALORE REFINERY AND PETROCHEMICALS LIMITED

Rotating Equipment Condition Monitoring — Field Inspection Report

Report No.	MRPL-INSP-2026-0905-PMP204	Inspection Date	05-Sep-2026
Equipment Tag	PMP-204	Unit	CDU-1 Pump House 3
Equipment Type	Centrifugal Booster Pump	SOP Reference	SOP-MNT-042
Inspector	R. Shetty	Shift	Day

Recorded Readings

Parameter	Measured Value	Limit (SOP-MNT-042)	Method
Vibration Velocity RMS	5.4 mm/s	Zone A <= 2.8 Zone D > 7.1	Handheld accelerometer
Bearing Seal Temperature	79.5 deg C	<= 80 deg C	IR thermal probe

Inspector Notes

Follow-up inspection. Noticeable increase in vibration since last reading; audible rattling near the coupling end during operation. Bearing housing warmer than previous visit. Recommend closer monitoring and scheduling a maintenance window if trend continues upward.

Preliminary Zone Indication (field estimate, not the deterministic SOP verdict)

Field estimate: Zone C (deteriorating, elevated but not yet critical per field observation).

Signed: _____ Date: _____